

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

September 20, 2006 Signature on File

TO: Ms. Kathy Sedlack, Principal

Martin Luther King Elementary School

FROM: Robert J. Krickovich, Coordinator, LEA

Facilities and Construction Management, Environmental Division

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 103A

On September 1, 2006 I conducted an assessment of FISH 103A at Martin Luther King Elementary School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Verda Farrow, Area Superintendent
Michaelle Pope, Area Director
Jeffrey S. Moquin, Director, Risk Management
Sheldon Dash, Project Manager, Facilities and Construction Management
Jerrod Neal, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

	King Elem	entary	School	Evaluation Requested September 1, 2006							
Time of Day	10:3	0 am]					E	Evaluation Date	Septe	ember 1, 2006
Outdoor Condi	tions	Ter	nperature	88	3.8	Relative Hur	nidity	61	Ambie	nt CO2	460
Fish	Fish Temperature Range		Range	Relative Humidity		Range		CO2	Range # Occupar		# Occupants
103A	74.4 72 - 78		54.8		30% - 60%	% - 60% 666		Max 700	> Ambi	ent 1	
Noticeable Odor Yes				sible water age / staining	Visible microbial growth?			Amount of material affected			
Ceiling Type	2 x 4 Lay In		No		No		None				
Wall Type	Plaster		Yes		Yes			10 Square Feet at Bookcase		Bookcase	
Flooring		Carpet		Yes			Yes		Standing Water - 6 square feet		
	C	lean	Minor D / Debr		Needs Cleaning	l		Correc	ctive Action Re	quired	
Ceiling	[Yes	No]	No						
Walls	[No	Yes		Yes		F	Repair/r	eplace as appr	opriate	
Flooring	No		Yes	Yes			Ren	nove an	nd replace as appropriate		
HVAC Supply	Grills	Yes	No]	No						
HVAC Return (Grills	Yes	No]	No						
Ceiling at Sup Grills	ply [Yes	No]	No						
Surfaces in Ro	oom	Yes	No		No						

IAQ Assessment

1611

Location Number

Observations

Findings:

- Elevated moisture content and visible microbial growth wall at bookcase FISH 103A
- Standing water, elevated moisture and visible microbial growth on carpet
- FISH 103 Carpet wet at wall to FISH 103A

Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of water intrusion into room
- Repair/replace water damaged wall material as appropriate wall at bookcase in FISH 103A
- Repair/replace bookcase in FISH 103A
- Remove carpet in FISH 103, 103A, 103C, 103D and 103E and replace with tile