

Temp 79.6 RH 54.5 CO2 444

FISH	Answer	Recommendation
202	No leaks identified in FISH 202. Signs of previous water intrusion as evidenced by stained ceiling tiles. FISH 202B (closet) appears to have a leak from above. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
208	Environmental parameters were not within acceptable range at the time of assessment.. Humidity was slightly elevated.	Physical Plant Operations to evaluate HVAC for proper operation and repair as appropriate to lower humidity.
221	Signs of water intrusion. Leak identified.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
307	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate HVAC for proper operation and repair as appropriate to lower humidity.
335	Leak under sink identified.	Physical Plant Operations to evaluate and repair as appropriate.