

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

October 10, 2	2008 Signature on File	For Custodial Supervisor Use Only
TO:	Ms. Pamela Govoni, Principal Lloyd Estates Elementary School	Custodial Issues Addressed
FROM:	Edward See, Project Manager Risk Management Department	Custodial Issues Not Addressed
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 206	

On October 8, 2008 I conducted an assessment of FISH 206 at **Lloyd Estates Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Leontine Butler, Area Superintendent Dr. Margaret Underhill, Area Director Jeffrey S. Moquin, Director, Risk Management Robert Goode, Project Manager, Facilities and Construction Management Dane Ramson, Broward Teachers Union Roy Jarrett, Federation of Public Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

	IAQ Assessment		sessment	Location Number		1091		
Lloyd Estates Eleme			entary School		Evaluation Requested		September 25, 2008	
Time of Day	3:15 pm				Ev	aluation Date	Octobe	r 8, 2008
Outdoor Condition	ons Temp	perature	81.9	Relative Humidity	53.9	Ambie	nt CO2	540
Fish Te	mperature R	ange Rela	ative Humidity	Range	CO2	Ran	ige #	Occupants
206	72 72	- 78	59.2	30% - 60%	427	Max 700	> Ambient	3
Noticeable Odo	r No		Visible water nage / staining	Visible micro growth?		Amount of mat affected	terial	
Ceiling Type	2 x 2		No	No			None	
Wall Type	Drywall/Plas	ter	No	No			None	
Flooring	12 x 12 Viny	/l	No	No	Γ		None	
Ceiling	Clean Yes	Minor Dust / Debris No	Needs Cleaning No		Correct	ive Action Re	equired	
Walls	Yes	No	No					
Flooring	Yes	Νο	No					
HVAC Supply G	rills Yes	No	No					
HVAC Return G	rills Yes	Νο	No					
Ceiling at Suppl Grills	y No	Yes	Yes		Clear	n as appropria	ate	
Surfaces in Roo	m Yes	No	No					

Observations

Findings: - Dust build up on ceiling at HVAC supply grills

Recommendations:

<u>Site Based Maintenance:</u> - Clean ceiling tiles at HVAC supply grills - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate