

managing risk with responsibility

Aston A. Henry, Director	
Risk Management Departmer	١t

 Telephone:
 754 321-1900

 Fax:
 754 321-1917

April 24, 2014	Signature on File	For Custodial Supervisor Use Only		
TO:	Matthew Whaley, Principal Meadowbrook Elementary School	Custodial Issues Addressed Custodial Issues Not Addressed		
FROM:	Richard Rosa, Project Manager Risk Management Department			
SUBJECT:	Indoor Air Quality (IAQ) Assessment			

On March 25, 2014, I conducted an assessment at **Meadowbrook Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Director, Risk Management Sonja Coley, Senior Project Manager, Facilities & Construction Broward Teachers Union Federation of Public Employees

RR/tc Enc.

Fish Temperature Range Relative Humidity Range CO ² Range # Occupants P-545C 70.7 72 - 78 63.5 30% - 60% 435 MAX 700 > Ambient Noticeable Odor No Visible water damage / staining? Visible microbial growth? Amount of material affected Ceiling 2' X 4' Lay in Yes No 2 tiles < 1 sq ft Walls Drywall Yes No 70 sq ft Floor 12" x 12" Vinyl No No 70 sq ft Grills Clean No HVAC Supply Grills Clean No HVAC Return Grills Clean No Flooring Clean No Inside of Supply Duct Clean NA Duct Clean N/A Room Surfaces No Ceiling at Supply Grills Clean N/A Cleaners in Room No Room Cluttered No Food if Stored in Room is in Sealed Containers N/A Air Fresheners in Room No Hechanical Equipment Location Window unit M Cleaners in Room Clean N/A Fresh Air Intake Location Window unit Y Fresh Air Intake Free o	IAQ Assessment						
Fish Temperature Range Relative Humidity Range CO2 Range # Occupants P-545C 70.7 72 - 78 63.5 30% - 60% 435 MAX 700 > Ambient Noticeable Odor No Visible water damage / staining? Visible microbial growth? Amount of material affected Ceiling 2' X 4' Lay in Yes No 2 tiles < 1 sq ft	Meadowbrool	< Elementary Evaluation Date	e March 25, 2014	Time of Day	0:45		
P-545C 70.7 72 - 78 63.5 30% - 60% 435 MAX 700 > Ambient Noticeable Odor No Visible water damage / staining? Visible microbial growth? Amount of material affected Ceiling 2' X 4' Lay in Yes No 2 tiles < 1 sq ft	Outdoor Conditions Temper	rature 77.7 Relative	Humidity 81.3	Ambient CO2 4	31		
Noticeable Odor No Visible values material affected Ceiling 2' X 4' Lay in Yes No 2 tiles < 1 sq ft			425	MAX 700 >	ccupants		
Walls CleanNoGrills CleanNoWalls CleanNoInside of Supply Duct CleanN/AInside of Return Duct CleanN/ARoom Surfaces CleanNoCeiling at Supply Grills CleanN/aN/AN/ATrash RemovedYesExhaust Fans Working Grills CleanN/AUnapproved Chemicals / Cleaners in RoomNoSigns of PestsNoDrain Traps Wet in Sealed ContainersN/AAir Fresheners in RoomNoMechanical Equipment LocationWindow unitMechanical Room CleanN/AFilters Installed ProperlyYesFilters CleanNoInside of HVAC Unit CleanFresh Air Intake LocationWindow unitNoYesFresh Air Intake Free of ObstructionYesPollutant Sources Near Air IntakeGrass and landscapeYesYesYes	Ceiling 2' X 4' Lay in Walls Drywall	staining? Yes Yes	growth?	material affected 2 tiles < 1 sq ft			
Signs of Pests No Drain Traps Wet N/A Air Fresheners in Room No Room Cluttered No Food if Stored in Room is in Sealed Containers N/A Air Fresheners in Room No Mechanical Equipment Location Window unit Mechanical Room Clean N/A Filters Installed Properly Yes Filters Clean No Inside of HVAC Unit Clean N/A Condensate Pan Clean N/A Cooling Coil Clean No Fresh Air Intake Location Window unit Yes Follutant Sources Near Air Grass and landscape Yes Yes	Walls CleanNoFlooring CleanYesRoom SurfacesNo	Grills Clean Inside of Supply Duct Clean Ceiling at Supply	N/A	Grills Clean Inside of Return			
Filters Installed Properly Yes Filters Clean No Inside of HVAC Unit Clean N/A Condensate Pan Clean N/A Cooling Coil Clean No V/A V/A Fresh Air Intake Location Window unit V Fresh Air Intake Free of Obstruction Yes Pollutant Sources Near Air Intake Grass and landscape V Yes	Signs of Pests No	Drain Traps Wet Food if Stored in Room is	N/A	Cleaners in Room Air Fresheners			
Pollutant Sources Near Air Grass and landscape of Obstruction Yes	Filters Installed Properly	s Filters Clean					
Observations	Pollutant Sources Near Air				Yes		
	Observations						

Replace water damaged wall board, approx. 70 sq ft. under the West HVAC window unit; Remove marker board and evaluate the extent of water damage. The moisture meter observed wet wall material around the Northwest corner, two feet on north wall and 8 feet on west wall. Window unit condensate drain is the possible cause of water intrusion. Clean both coils. Monitor the temperature in classroom, keep thermostat between 72 -78 degrees. Wipe down South door with Wexcide.

Corrective Actions to be Completed by Site Based Staff

		_
Replace stained	ceiling tiles by lights	▼
Thoroughly clea	an elevated surfaces	▼
Remove and	replace A/C filters	▼
Monitor thermostat	in room 72 - 78 degrees	▼
Wipe down doo	or stain and monitor	▼
Vacuum/wexcide	both window unit grills	▼
		▼
		▼

Corrective Actions to be Completed by PPO

Repair HVAC to reduce Humidity levels	▼
Evaluate and repair cause of water damage	▼
Remove and replace wall material as necessary	▼
Clean both window unit coils	▼
Evaluate the weather stripping for both doors	▼
	▼
See observations for additional information	▼