

February 14, 2014

# managing risk with responsibility

Aston A. Henry, Director Telephone: 754 321-1900 Risk Management Department Fax: 754 321-1917

Signature on File

TO: Michelle Garcia, Principal

Oakland Park Elementary School

FROM: Robert Krickovich, Coordinator I, LEA

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

For Custodial Supervisor Use Only			
	Custodial Issues Addressed		
	Custodial Issues Not Addressed		

On February 12, 2014, I conducted an assessment at **Oakland Park Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Director, Risk Management Sonja Coley, Senior Project Manager, Facilities & Construction Broward Teachers Union Federation of Public Employees

RK/tc Enc.

Odor of old wood - classroom in old building - Window not sealed properly, not installed properly - Heavy dust and debris inside of mechanical room

# Corrective Actions to be Completed by Site Based Staff

Jotan
▼
▼
▼
▼
▼
▼
▼
▼

# Corrective Actions to be Completed by PPO

▼
▼
▼
▼
▼
▼
▼
▼

Outdoor Conditions Tempo	erature 82.2 Relative	e Humidity 61.7	Ambient CO2 4	71
		Range CO <sup>2</sup> 9% - 60% 557		ccupants 2
Noticeable Odor Yes	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' X 4' Lay in	No	No		
Walls Plaster	No	No		
Floor 12" x 12" Vinyl	No	No		
Ceiling Clean Yes Walls Clean Yes	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	Yes
Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	No
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	No		
Trash Removed Yes	Exhaust Fans Working	Yes	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps Wet	Yes	Air Fresheners	No
Room Cluttered No	Food if Stored in Room is in Sealed Containers	N/A	in Room	[NO]
Mechanical Equipment Locatio	on FISH 411		Mechanical Room Clean	No
Filters Installed Properly	es Filters Clean	No	Inside of HVAC Unit Clean	Yes
Condensate Pan Clean Y	'es Cooling Coil Clean	Yes		
Fresh Air Intake Location	Outside of Room	▼	Fresh Air Intake Free	Yes
Pollutant Sources Near Air Intake	None	▼	of Obstruction	

# **Observations**

Odor of old wood - classroom in old building - Heavy dust build up on HVAC supply grills and ceilings at supply grills -Heavy dust and debris inside of mechanical room

# **Corrective Actions to be Completed by Site Based Staff**

<b>211</b>
▼
▼
▼
▼
•
•
•
▼

# Corrective Actions to be Completed by PPO

Corrective Actions to be Completed by FFO	
Replace ceiling tiles at HVAC supply grills - Cuts	▼
Clean inside of return box in room 405	▼
	▼
	•
	▶
	▶
	▼
	▼

- Water damaged wall material at door to restroom 406A - Heavy dust and debris inside of mechanical room

# Corrective Actions to be Completed by Site Based Staff

▼
▼
▼
▼
▼
▼
▼
▼

### Corrective Actions to be Completed by PPO

Corrective Actions to be completed by 1.1.0			
Replace ceiling tiles at HVAC supply grills - Cuts			
Evaluate and repair cause of water damaged	▼		
wall material near door to restroom 406A	▼		
Remove and replace wall material as necessary			
	▼		
Replace threshold of room 410 to prevent	▼		
dirt being blown into room	▼		
	▼		