

Temp 80 RH 62 CO2 402

FISH	Answer	Recommendation
131	Temperature was low at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
136	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
203B	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
218	Stale odor in room.	Physical Plant Operations to evaluate and repair as appropriate.
404	Caulking at sink backsplash is damaged/missing.	Physical Plant Operations to evaluate and repair as appropriate.
406	Caulking at sink backsplash is damaged/missing.	Physical Plant Operations to evaluate and repair as appropriate.
	Gaps in doors identified at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
407	Caulking at sink backsplash is damaged/missing.	Physical Plant Operations to evaluate and repair as appropriate.
409	Caulking at sink backsplash is damaged/missing.	Physical Plant Operations to evaluate and repair as appropriate.
	CO2 level was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
502	Caulking at sink backsplash is damaged/missing.	Physical Plant Operations to evaluate and repair as appropriate.
503	Sink backsplash is damaged.	Physical Plant Operations to evaluate and repair as appropriate.
	Humidity level was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
504	Caulking at sink backsplash is damaged/missing.	Physical Plant Operations to evaluate and repair as appropriate.
	CO2 level was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
	No floor drain in room.	
509	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
510	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
	Caulking at sink backsplash is damaged/missing.	Physical Plant Operations to evaluate and repair as appropriate.

Temp 80 RH 62 CO2 402

601	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
	CO2 level was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
	Caulking at sink backsplash is damaged/missing.	Physical Plant Operations to evaluate and repair as appropriate.
602	CO2 level was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
604	CO2 level was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
	Gaps in doors identified at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
608	Gaps in doors identified at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.