THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

TELEPHONE (754) 321-4200

FACSIMILE: (754) 321-4285

October 5, 20	017 Signature on File	For Custodial Supervisor Use Only
TO:	Marsha Wagner, Principal Pembroke Lakes Elementary	Custodial Issues Addressed
FROM:	Alison Witoshynsky, Project Manager Environmental Health & Safety Department	Custodial Issues Not Addressed
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On October 4, 2017, I conducted an assessment at **Pembroke Lakes Elementary School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

cc: Sam Bays, Director, Maintenance Operations Shelley Meloni, Director, Pre-Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Greg Neiman, Area Supervisor, Zone 1 Kurt Wirz, Area Manager Trades Gerald Devio, Supervisor II Custodial Benjamin Osborne, Supervisor II Custodial Mark Murray, Supervisor II Custodial Broward Teachers Union Federation of Public Employees

	IAQ Assessr	nent		
Pembroke Lake	es Elementary Evaluation Dat	e October 4, 2017	Time of Day 12:3	30 PM
Outdoor Conditions Tempe	erature 88.4 Relative	Humidity 63.7	Ambient CO2 46	64
		Range CO ² % - 60% 1276		cupants 22
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' X 4' Lay in	No	No	4 CT	
Walls Tack Board	Yes	No	small stain above cabin	nets
Floor 12" x 12" Vinyl	No	No		
Ceiling CleanNoWalls CleanNoFlooring CleanYesRoom SurfacesNo	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply	Yes	HVAC Return Grills Clean Inside of Return Duct Clean	Yes
Clean	Grills Clean	Yes		
Trash Removed Yes Signs of Pests No	Exhaust Fans Working Drain Traps Wet	N/A Yes	Unapproved Chemicals / Cleaners in Room	No
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners in Room	No
Mechanical Equipment Locatio	n FISH 170		Mechanical Room Clean	Yes
Filters Installed Properly	es Filters Clean	Yes	Inside of HVAC Unit Clean	Yes
Condensate Pan Clean	es Cooling Coil Clean	Yes		
Fresh Air Intake Location	Roof top	▼	Fresh Air Intake Free of Obstruction	N/A
Pollutant Sources Near Air Intake	Not readily accessible	▼	of obstruction	
Observations				

Observations

Occupant reports mildew in the classroom. This classroom is for science. There is lots of stuff within the cabinets as well as items taped to the walls and cabinet faces. Plants were present at the back of the room. In addition, FISH 183A is a storage closet, server room including at least 4 ceiling tiles needing cuts likely from roof leaks (J815803). HFSP reports that A/C for this area has gone under major renovations. Relative humidity and CO2 are near the high end of our range, additional adjustments may be needed, however, this room is likely near the end of the duct line which may be contributing.

Corrective Actions to be Completed by Site Based Staff

Room too cluttered to clean properly		
Encourage occupant to reduce clutter	▼	
Remove live plants from room		
Soil can be source of microbial growth	▼	
Remove and replace stained ceiling tile	▼	
Follow up w/ COMPASS on roof work order(s)	▼	
Clean dust from wall surfaces	▼	
Thoroughly clean elevated/horizontal surfaces	▼	

Corrective Actions to be Completed by PPO

▼	Evaluate and repair HVAC system as needed		
▼	Repair HVAC to Reduce CO2 Levels		
▼	Repair HVAC to Reduce Humidity Levels		
. ▼	Evaluate and repair cause of stained ceiling tile		
▼	likely related to roof leaks (J815803) working		
▼ 1	Install new ceiling tile upon repair, cuts needed		
▼	Evaluate fresh air damper at HVAC		
▼	Clean HVAC return grills and drops		