

Report: PPO

PINES LAKES ELEMENTARY

Walkthrough Date: 03/15/2007 Temp RH CO2

Outdoor Parameters: 70.0 57.5 820

Room	Priority	Responsible	Answer	Recommendation
120	Inside Parameters:	Temp 72.7	RH 52.9	CO2 861
1		PPO	Signs of water intrusion. Stained ceiling tiles. 5- over sink	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
126	Inside Parameters:	Temp 69.8	RH 58.6	CO2 885
1		PPO	Signs of water intrusion. Stained ceiling tiles. 5 stained at exterior wall	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
131	Inside Parameters:	Temp 71.7	RH 51.3	CO2 987
2		PPO	Exhaust fan is not functioning properly. room 131A	Physical Plant Operations to evaluate and repair as appropriate.
132	Inside Parameters:	Temp 71.5	RH 50.7	CO2 916
1		PPO	Signs of water intrusion. Stained ceiling tiles. 2 stained tiles over sink	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
134	Inside Parameters:	Temp 71.4	RH 51.2	CO2 899
2		PPO	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
135A	Inside Parameters:	Temp	RH	CO2
		71.1	51.9	900

- 2 PPO Bathroom exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.
- 2 PPO Exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
141	Inside Parameters:	Temp	RH	CO2
		72.5	50.1	1212

- 1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
- 2 PPO Bathroom exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.