

# managing risk with responsibility

Aston A. Henry, Supervisor Telephone: 754 321-1900 Risk Management Department Fax: 754 321-1917

January 4, 2011 Signature on File

TO: Ms. Robin David, Principal

**Royal Palm Elementary School** 

FROM: Edward See, Project Manager

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

**FISH 301** 

For	Custodial Supervisor Use Only					
	Custodial Issues Addressed					
	Custodial Issues Not Addressed					
	Custodial Issues Not Addressed					

On November 16, 2010 I conducted an assessment of FISH 301 at **Royal Palm Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Dr. Desmond Blackburn, Area Superintendent

Jan Beal, Area Director

Jeffrey S. Moquin, Executive Director, Support Operations

Aston Henry, Supervisor, Risk Management

Sam Bays, Project Manager, Facilities and Construction Management

Jerrod Neal, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

Royal Palm Elementary School							Evaluation Requested November 4, 2010			
Time of Day						E	Evaluation Date	Noveml	ber 16, 2010	
Outdoor Condit	tions	Te	emperature	83.9	Relative Humidi	ty 54.5	5 Ambie	nt CO2	401	
	empera		Range	Relative Humidity		CO2	Ran	_	# Occupants	
301	76		72 - 78 ¬	59.8	30% - 60% Visible mid	930	Max 700		nt 2	
Noticeable Odor Yes				Visible water damage / stainir	robiai 1?	Amount of material affected				
Ceiling Type	2 x 4 Lay In		y In	Yes	No	No		2 ceiling tiles		
Wall Type		Drywall		No	No	]	None			
Flooring	1	12 x 12 Vinyl		No No			None			
	C	Clean	Minor D / Debr			Correc	ctive Action Re	quired		
Ceiling		No	Yes	Yes		Remove a	and replace cei	ling tiles		
Walls		Yes	No	No						
Flooring		Yes	No	No						
HVAC Supply	Grills	Yes	No	No						
HVAC Return (	Grills	Yes	No	No						
Ceiling at Supp Grills	ply	Yes	No	No						
Surfaces in Ro	om	Yes	No	No						
bservations										

**IAQ Assessment** 

1851

**Location Number** 

## 0

## **Findings**

- 2 stained ceiling tiles
- Humidity level was elevated
- Dust build up on area rug
- Stuffed animals in room
- Musty odor in room

## Site Based Maintenance:

- Remove and replace stained ceiling tiles and monitor. If stains return contact COMPASS to generate a work order for Physical Plant Operations to evaluate for cause.
- Thoroughly clean area rug
- Occupant to thoroughly clean stuffed animals on a regular basis or remove from room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level

NOTE: Work order EQ01558 generated