

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

September 30, 2005

Signature on File

TO: Mr. Robert Gibson, Principal

Sanders Park Elementary School

FROM: Kenneth I. Partee, Project Manager, Occupational Health and Environmental

Control

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 351VE, 780 and 781

On September 2, 2005 the IAQ Assessment Team conducted an assessment of FISH 351VE, 780 and 781 at **Sanders Park Elementary School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent

Jackie Haywood, Area Director

Jeffrey S. Moquin, Director, Risk Management

Jack Cooper, Senior Project Manager, Facilities and Construction Management

LaFrances Trotter, Broward Teachers Union

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc Enc.

Fish Temperature Range 72 - 78	Sanders Park Elementary School Evaluation Requested September 1, 2005
Fish Temperature Range Relative Humidity Range CO2 Range # Occupants 351VE 72 - 78 30% - 60% Max 700 > Ambient Max 700	Time of Day 12:45 pm Evaluation Date September 2, 2005
351VE	Outdoor Conditions Temperature 96.6 Relative Humidity 49.7 Ambient CO2 462
Wall Type Plaster No No No None Flooring Tile No No No None Clean Minor Dust / Debris Cleaning Corrective Action Required Ceiling Yes No No No Flooring Yes No	351VE 72 - 78 30% - 60% Max 700 > Ambient Noticeable Odor No Visible water Visible microbial Amount of material
Flooring Tile No No No None Clean Minor Dust / Debris Cleaning Corrective Action Required Ceiling Yes No No No Walls Yes No No No Flooring Yes No	Ceiling Type 2 x 4 Lay In No None
Clean Minor Dust / Debris Cleaning Corrective Action Required Ceiling Yes No No Walls Yes No No Flooring Yes No No HVAC Supply Grills Yes No No HVAC Return Grills Yes No No Ceiling at Supply Yes No No Ceiling at Supply Yes No No Surfaces in Room Yes No No Surfaces in Room Yes No No Recommendations: Site Based Maintenance: - Flush water in portable weekly Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:	Wall Type Plaster No None
Ceiling Yes No No No Walls Yes No No No Walls Yes No No No Flooring Yes No No No HVAC Supply Grills Yes No No No Geiling at Supply Yes No No No Ceiling at Supply Yes No No No Ceiling at Supply Yes No No No Surfaces in Room Yes No No Surfaces in restroom is not working - Dust and debris on HVAC filters - Water in portable is not used regularly Recommendations: Site Based Maintenance: - Remove and replace HVAC filters - Flush water in portable weekly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:	Flooring Tile No No None
Walls Yes No No Flooring Yes No No HVAC Supply Grills Yes No No HVAC Return Grills Yes No No Ceiling at Supply Yes No No Ceiling at Supply Yes No No Grills Surfaces in Room Yes No No Deservations Findings: - Exhaust fan in restroom is not working - Dust and debris on HVAC filters - Water in portable is not used regularly Recommendations: Site Based Maintenance: - Remove and replace HVAC filters - Flush water in portable weekly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:	
Flooring Yes No No HVAC Supply Grills Yes No No HVAC Return Grills Yes No No Ceiling at Supply Yes No No Grills Surfaces in Room Yes No No Servations Findings: - Exhaust fan in restroom is not working - Dust and debris on HVAC filters - Water in portable is not used regularly Recommendations: Site Based Maintenance: - Remove and replace HVAC filters - Flush water in portable weekly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:	Ceiling Yes No No
HVAC Supply Grills Yes No No No HVAC Return Grills Yes No No No Ceiling at Supply Yes No No No Surfaces in Room Yes No No No Surfaces in Room Yes No No No Servations Findings: - Exhaust fan in restroom is not working - Dust and debris on HVAC filters - Water in portable is not used regularly Recommendations: Site Based Maintenance: - Remove and replace HVAC filters - Flush water in portable weekly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:	Walls Yes No No
HVAC Return Grills Yes No No Ceiling at Supply Yes No No Grills Surfaces in Room Yes No No Descriptions Findings: - Exhaust fan in restroom is not working - Dust and debris on HVAC filters - Water in portable is not used regularly Recommendations: Site Based Maintenance: - Remove and replace HVAC filters - Flush water in portable weekly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:	Flooring Yes No No
Ceiling at Supply Yes No No Surfaces in Room Yes No No Servations Findings: - Exhaust fan in restroom is not working - Dust and debris on HVAC filters - Water in portable is not used regularly Recommendations: Site Based Maintenance: - Remove and replace HVAC filters - Flush water in portable weekly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:	HVAC Supply Grills Yes No No
Surfaces in Room Yes No No Descriptions Findings: - Exhaust fan in restroom is not working - Dust and debris on HVAC filters - Water in portable is not used regularly Recommendations: Site Based Maintenance: - Remove and replace HVAC filters - Flush water in portable weekly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:	HVAC Return Grills Yes No No
bservations Findings: - Exhaust fan in restroom is not working - Dust and debris on HVAC filters - Water in portable is not used regularly Recommendations: Site Based Maintenance: - Remove and replace HVAC filters - Flush water in portable weekly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:	
Findings: - Exhaust fan in restroom is not working - Dust and debris on HVAC filters - Water in portable is not used regularly Recommendations: Site Based Maintenance: - Remove and replace HVAC filters - Flush water in portable weekly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:	Surfaces in Room Yes No No
	Findings: - Exhaust fan in restroom is not working - Dust and debris on HVAC filters - Water in portable is not used regularly Recommendations: Site Based Maintenance: - Remove and replace HVAC filters - Flush water in portable weekly - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate Physical Plant Operations Division:

IAQ Assessment

0891

Location Number

	Sanders Park E	lementary School		Evaluation R	equested September 1, 2005				
Time of Day	12:45 pm			Evalu	ation Date September 2, 2005				
Outdoor Condition	ons Temperat	ure 96.6	Relative Humidity	49.7	Ambient CO2 462				
Fish Te	mperature Range 90.6 72 - 78		/ Range	CO2	Range # Occupants Max 700 > Ambient 1				
Noticeable Odor		Visible water	Visible micro	bbial Am	ount of material				
Ceiling Type	2 x 4 Lay In	damage / stainin	g? growth?		affected None				
Wall Type	Plaster	No	No		None				
Flooring	Tile	No	No		None				
		or Dust Needs Debris Cleaning		Corrective	Action Required				
Ceiling	Yes	No No							
Walls	Yes	No No							
Flooring	Yes	No No							
HVAC Supply G	rills Yes	No No							
HVAC Return Gr	rills Yes	No							
Ceiling at Supply Grills	y Yes	No No							
Surfaces in Roo	m Yes	No No							
Dbservations									
Findings: - HVAC system wa	as not working at the	time of assessment							
Recommendation	ns:								
Site Based Maintenance: - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate									
Physical Plant Operations Division: - Evaluate and repair HVAC system to lower temperature and humidity									

IAQ Assessment

0891

Location Number

Sanders Park Elementary School						Evaluation Requested September 1, 2005			
Time of Day 12:	45 pm				Eva	luation Date	September	2, 2005	
Outdoor Conditions	Tempera	96.6	Rela	ative Humidity	49.7	Ambier	nt CO2 40	62	
Fish Tempe 781 72 Noticeable Odor	72 - 7 Yes	78 55. Visibl	6 30% e water	Range % - 60% Visible micro	734 bial A	—l amount of mate	> Ambient	15	
Ceiling Type	2 x 4 Lay In	— <u> </u>	/ staining?	growth?		affected	None	——————————————————————————————————————	
Wall Type	Plaster	= =	lo	No		ı	None		
Flooring	Tile		lo	No			None		
(nor Dust Debris C	Needs Cleaning		Correctiv	ve Action Rec	quired		
Ceiling	Yes	No	No						
Walls	Yes	No	No						
Flooring	Yes	No	No						
HVAC Supply Grills	Yes	No	No						
HVAC Return Grills	Yes	No	No						
Ceiling at Supply Grills	Yes	No	No						
Surfaces in Room	Yes	No	No						
Findings: - One missing ceiling to the commendations: Site Based Maintenary - Replace missing ceiling to the continue to monitor to appropriate	g of new buildir nce: ing tile		crobial growt	h as well as dus	t and debri	s accumulatio	n and clean a	as	

IAQ Assessment

0891

Location Number