

Temp 78.3 RH 48.4 CO2 484

<b>FISH</b>	<b>Answer</b>	<b>Recommendation</b>
1328	Gaps in doors identified at the time of assessment. Weatherstrip on door leading to outside.	Physical Plant Operations to evaluate and repair as appropriate.
807	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.