

managing risk with responsibility

Aston A. Henry, Supervisor Telephone: 754 321-1900 Risk Management Department Fax: 754 321-1917

December 14, 2010 Signature on File

TO: Ms. Amada Walker, Principal

Silver Palms Elementary School

FROM: Edward See, Project Manager

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 124

On December 9, 2010 I conducted an assessment of FISH 124 at **Silver Palms Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Dr. Joel Herbst, Area Superintendent

Valerie Wanza, Area Director

Jeffrey S. Moquin, Executive Director, Support Operations

Aston Henry, Supervisor, Risk Management

Sonja Coley, Project Manager, Facilities and Construction Management

Steve Feldman, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

	Evaluati	ion Requested	Decemb	er 6, 2010				
Time of Day					E	Evaluation Date	Decemb	per 9, 2010
Outdoor Conditions Temperature 57.7 Relative Humidity 65.1 Ambient CO2 395								
Noticeable Odd Ceiling Type Wall Type	73.1 7 or No 2 x 4 Lay Drywall	2 - 78 dam	ive Humidity 50.1 (isible water age / staining? No No	Range 80% - 60% Visible mic growth No		Amount of material affec	> Ambien	Occupants t 5
Flooring	12 x 12 Vi	nyl	No]	None		
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Re	quired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply C	Grills Yes	No	No					
HVAC Return G	Grills Yes	No	No					
Ceiling at Supp Grills	oly Yes	No	No					
Surfaces in Roo	om Yes	No	No					

IAQ Assessment

3491

Location Number

Observations

Findings

- Advised previous water leak from water heater in 134 with standing water in FISH 124 and hallways. Physical Plant Operations facilitated clean up immediately. No signs of moisture found at the time of the assessment.
- Occupant in FISH 124 and 127 stated musty odor in the mornings. No odor detected at the time of the assessment. Advised HFSP to contact Risk Management to report odor when prevalent.
- FISH 193 (AHU room) filters not taped together
- 1/4" gap in outside door of somat area in cafeteria next to FISH 127, potential for odors
- No signs of water intrusion or microbial growth at the time of the assessment

Site Based Maintenance:

- Ensure that filters are taped together in AHU's
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate and repair gap in outside door of somat area in cafeteria next to FISH 127

NOTE: Work order EQ01575 generated