

managing risk with responsibility

Aston A. Henry, Director
Risk Management Departmen

 Telephone:
 754 321-1900

 Fax:
 754 321-1917

September 9, 2	014 Signature on File	For Custodial Supervisor Use Only
TO:	Michael Breslaw, Principal Tradewinds Elementary School	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Dan Meyer, Project Manager Risk Management Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On September 8, 2014, I conducted an assessment at **Tradewinds Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities & Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Director, Risk Management Sonja Coley, Senior Project Manager, Facilities & Construction Broward Teachers Union Federation of Public Employees

DM/tc Enc.

	IAQ Assess	ment		
Tradewinds	Elementary Evaluation Dat	te September 8, 2014	Time of Day 11:	30 AM
Outdoor Conditions Tempera	ture 87.3 Relative	e Humidity 68.8	Ambient CO2 4	30
		Range CO ² % - 60% 101 ²		ccupants 2
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling2' X 4' Lay inWallsDrywallFloor12" x 12" Vinyl	Yes No No	No No No	7 tiles	
Ceiling Clean Yes Walls Clean Yes Flooring Clean Yes	HVAC Supply Grills Clean Inside of Supply Duct Clean	Yes	HVAC Return Grills Clean Inside of Return Duct Clean	Yes
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	Yes		
Trash RemovedYesSigns of PestsNoRoom ClutteredNo	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	Yes Yes	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No No
Mechanical Equipment Location Filters Installed Properly Yes Condensate Pan Clean Yes	7	Yes	Mechanical Room Clean Inside of HVAC Unit Clean	Yes
Fresh Air Intake Location Pollutant Sources Near Air Intake	Thru exterior wall No	▼	Fresh Air Intake Free of Obstruction	Yes
Observations Room has roof leaks. School has damper is not working. Filters re		repairs. No signs of n	nicrobial growth. Outside	air

Corrective Actions to be Completed by Site Based Staff

▼
▼
▼
▼
▼
▼
▼
▼

Expedite roof repairs	▼
Repair fresh air damper in the mechanical room	▼
Check exterior window caulking	▼
	▼
	▼
	▼
	▼
	▼

	IAQ Assess	ment		
Tradewinds	Elementary Evaluation Dat	te September 8, 2014	Time of Day 11:3	30 AM
Outdoor Conditions Tempera	ature 87.3 Relative	e Humidity 68.8	Ambient CO2 43	0
		Range CO ² % - 60% 934	Range # Oc MAX 700 > Ambient	cupants 25
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling2' X 4' Lay inWallsDrywallFloor12" x 12" Vinyl	Yes No No	No No	3 tiles	
Ceiling Clean Yes Walls Clean Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean Inside of Return	Yes
Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Duct Clean	Yes
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	Yes		
Trash Removed Yes	Exhaust Fans Working	Yes	Unapproved Chemicals / Cleaners in Room	No
Signs of PestsNoRoom ClutteredNo	Drain Traps Wet Food if Stored in Room is in Sealed Containers	Yes	Air Fresheners in Room	No
Mechanical Equipment Location	FISH #189		Mechanical Room Clean	Yes
Filters Installed Properly Yes	Filters Clean	Yes	Inside of HVAC Unit Clean	Yes
Condensate Pan Clean Yes	Cooling Coil Clean	Yes		
Fresh Air Intake Location Pollutant Sources Near Air	Thru exterior wall	▼	Fresh Air Intake Free of Obstruction	Yes
Intake				
Observations Room has roof leaks. School ha damper is not working. Filters re				air

Corrective Actions to be Completed by Site Based Staff

▼
▼
▼
▼
▼
▼
▼
▼

Expedite roof repairs	▼
Repair fresh air damper in the mechanical room	▼
Check exterior window caulking	▼
	▼
	▼
	▼
	▼
	▼

	IAQ Assess	ment	
Tradewinds	Elementary Evaluation Dat	September 8, 2014	Time of Day 11:30 AM
Outdoor Conditions Temper	ature 87.3 Relative	e Humidity 68.8	Ambient CO2 430
		Range CO ² % - 60% 1015	
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected
Ceiling2' X 4' Lay inWallsDrywallFloor12" x 12" Vinyl	Yes No No	No No	14 tiles
Ceiling Clean Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean Yes
Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Yes
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	Yes	
Trash Removed Yes	Exhaust Fans Working	Yes	Unapproved Chemicals / Cleaners in Room No
Signs of PestsNoRoom ClutteredNo	Drain Traps Wet Food if Stored in Room is in Sealed Containers	Yes	Air Fresheners No in Room
Mechanical Equipment Location	FISH #189		Mechanical Room Clean Yes
Filters Installed Properly Ye	s Filters Clean	Yes	Inside of HVAC Unit Clean Yes
Condensate Pan Clean Ye	s Cooling Coil Clean	Yes	
Fresh Air Intake Location Pollutant Sources Near Air	Thru exterior wall	▼	Fresh Air Intake Free Yes
Intake	Νο	▼	
Observations			
			nicrobial growth. Outside air n between classrooms. Excessive

Corrective Actions to be Completed by Site Based Staff

	_
Clean dust build up by windows	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼

Expedite roof repairs	▼
Repair fresh air damper in the mechanical room	▼
Check exterior window caulking	▼
	▼
	▼
	▼
	▼
	▼

	IAQ Assess	ment		
Tradewinds	Elementary Evaluation Dat	September 8, 2014	Time of Day 11:30	AM
Outdoor Conditions Tempera	ature 87.3 Relative	e Humidity 68.8	Ambient CO2 430	
		Range CO ² % - 60% 1006	Range # Occu MAX 700 > Ambient	2
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling2' X 4' Lay inWallsDrywallFloor12" x 12" Vinyl	Yes No No	No No	1 tile	
Ceiling CleanYesWalls CleanYesFlooring CleanYes	HVAC Supply Grills Clean Inside of Supply Duct Clean	Yes		Yes Yes
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	Yes		
Trash RemovedYesSigns of PestsNoRoom ClutteredNo	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	Yes Yes Yes	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No Yes
Mechanical Equipment Location Filters Installed Properly Yes Condensate Pan Clean Yes		Yes Yes		Yes Yes
Fresh Air Intake Location Pollutant Sources Near Air Intake	Thru exterior wall No	▼	Fresh Air Intake Free of Obstruction	Yes
Observations Room has roof leaks. School ha damper is not working. Filters re			icrobial growth. Outside air	·

Corrective Actions to be Completed by Site Based Staff

	_
Remove plug-in air freshener	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼

Expedite roof repairs	▼
Repair fresh air damper in the mechanical room	▼
Check exterior window caulking	▼
	▼
	▼
	▼
	▼
	▼