

Aston A. Henry, Task Assigned Director

managing risk with responsibility

754 321-1900

Telephone:

Risk Management Department		Fax: 754 321-1917
May 22, 2013	Signature on File	For Custodial Supervisor Use Only
TO:	Aimee Zekofsky, Principal West Hollywood Elementary School	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Richard Rosa, Project Manager Facilities Design and Construction	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On May 21, 2013, I conducted an assessment at **West Hollywood Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Directors, School Performance & Accountability
Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Task Assigned Director, Risk Management
Sonja Coley, Senior Project Manager, Facilities Design and Construction
Broward Teachers Union
Federation of Public Employees

RR/tc Enc.

IAQ Assessment

West Hollywood	Elementary Evaluation Date	te May 21, 2013	Time of Day 1	1:15		
Outdoor Conditions Tempera	ture 88.7 Relative	Humidity 59.1	Ambient CO2 4	28		
		Range <u>CO</u> % - 60% 434		cupants		
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected			
Ceiling 2' x 4'	No	No				
Walls Plaster/Tack Board Floor 12" x 12" Vinyl	Yes No	No No	< 2 sq ft			
Ceiling Clean Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	Yes		
Walls Clean No Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	Yes		
Room Surfaces No Clean	Ceiling at Supply Grills Clean	Yes				
Trash Removed Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No		
Signs of Pests Yes	Drain Traps Wet	No	Air Fresheners	No		
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers	N/A	in Room	INO		
Mechanical Equipment Location FISH 130A Mechanical Room Clean Yes						
Filters Installed Properly Yes	Filters Clean	Yes	Inside of HVAC Unit Clean	Yes		
Condensate Pan Clean Yes	Cooling Coil Clean	Yes				
Fresh Air Intake Location	Thru exterior wall	▼	Fresh Air Intake Free	Yes		
Pollutant Sources Near Air Intake	No	▼	of Obstruction			

Observations

Water damaged wall observed over the fire blanket by the ceiling grid, chilled water lines over that area above the drop ceiling. Also there is a small amount of water damage by the right portion of the elevated window sill. There is also water damaged cabinetry under the sink, it is dry but wexcide can't remove the staining, double door sink. There are signs of insects under the sinks, droppings, and traps etc. Boxes are everywhere, cluttering the area. There is water on the floor in 130A, condensate drain pipe needs to be adjusted over the drain.

Corrective Actions to be Completed by Site Based Staff

Contestive Actions to be completed by Oile Based Stan				
▼				
▼				
▼				
▼				
▼				
•				
▼				
▼				

Corrective Actions to be Completed by PPO

valuate and repair cause of water damage	▼		
Remove and replace wall material as necessary			
Adjust condensate pipe over condensate drain			
	▼		
	▼		
See observations above for additional details			
	▼		
	▼		