

Cooper City High
TfS IAQ Walkthrough
5-2-2008

FISH	Answer	Recommendation	Priority
012	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
101	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
102	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
102M	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
102N	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
103	ROOM NUMBER – no FISH sign on wall due to painting. Stained and missing ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
105	Ceiling tiles bowed with gaps.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
107	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
117	Gaps in doors.	Physical Plant Operations to evaluate and repair as appropriate.	1
117	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
134	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
139	Bowed and stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
139	Gaps in doors.	Physical Plant Operations to evaluate and repair as appropriate.	1
144	Gap in ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
148	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
152	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
154R	Damaged wall material.	Physical Plant Operations to evaluate and repair as appropriate.	1
154S	Damaged wall material.	Physical Plant Operations to evaluate and repair as appropriate.	1
155A	Damaged wall material.	Physical Plant Operations to evaluate and repair as appropriate.	1
155A	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
156	Damaged wall material with visible microbial growth. Teacher removed from room.	Physical Plant Operations to evaluate and repair as appropriate.	1
156	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
158	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
161	Damaged wall material.	Physical Plant Operations to evaluate and repair as appropriate.	1
161	Gaps in doors.	Physical Plant Operations to evaluate and repair as appropriate.	1
164	Gaps in doors.	Physical Plant Operations to evaluate and repair as appropriate.	1

Cooper City High
TfS IAQ Walkthrough
5-2-2008

FISH	Answer	Recommendation	Priority
164	Damaged wall material.	Physical Plant Operations to evaluate and repair as appropriate.	1
165	Damaged wall material.	Physical Plant Operations to evaluate and repair as appropriate.	1
165	Gaps in doors.	Physical Plant Operations to evaluate and repair as appropriate.	1
165	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
174A	Damaged wall material.	Physical Plant Operations to evaluate and repair as appropriate.	1
174A	Gaps in doors.	Physical Plant Operations to evaluate and repair as appropriate.	1
176A	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
199	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
203	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
230	Open ceiling tiles	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
243	Damaged wall material.	Physical Plant Operations to evaluate and repair as appropriate.	1
243	Gaps in doors.	Physical Plant Operations to evaluate and repair as appropriate.	1
243	Possible water intrusion.	Physical Plant Operations to evaluate for source of water intrusion and repair as appropriate.	1
243	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
244	No ventilation in storage room.	Physical Plant Operations to evaluate room for installation of supply and return ventilation.	2
263	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
265	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
292	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
292	Possible water intrusion.	Physical Plant Operations to evaluate for source of water intrusion and repair as appropriate.	1
604	Possible water intrusion.	Physical Plant Operations to evaluate for source of water intrusion and repair as appropriate.	1
604	Stained ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
616	Environmental parameters were within acceptable range at the time of assessment. However, Facility Serviceperson advised that they are manually overriding the system.	Physical Plant Operations to evaluate and repair as appropriate.	2
617	Possible water intrusion in hallway outside of FISH 617.	Physical Plant Operations to evaluate for source of water intrusion and repair as appropriate.	1
617	Stained ceiling tiles in hallway outside of FISH 617.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1
619	Bowed ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1

**Cooper City High
TfS IAQ Walkthrough
5-2-2008**

FISH	Answer	Recommendation	Priority
619	Possible water intrusion.	Physical Plant Operations to evaluate for source of water intrusion and repair as appropriate.	1
3445	Gap in ceiling tiles.	FM14431 has been generated for replacement of ceiling tiles throughout site.	1