THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

FACSIMILE: (754) 321-4285

TELEPHONE (754) 321-4200

November 20), 2017	Signature on File	For Custodial Supervisor Use Only
TO:	Charles Neely, Principa Cypress Bay High	al	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Alison Witoshynsky, P Environmental Health	,	
SUBJECT:	Indoor Air Quality (IA	Q) Assessment	

On November 16, 2017, I conducted an assessment at **Cypress Bay High School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

cc: Sam Bays, Director, Maintenance Operations
Shelley Meloni, Director, Pre-Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Greg Neiman, Area Supervisor, Zone 1
Kurt Wirz, Area Manager Trades
Gerald Devio, Supervisor II Custodial
Benjamin Osborne, Supervisor II Custodial
Mark Murray, Supervisor II Custodial
Broward Teachers Union

Federation of Public Employees

Entire NORTH Wall is wet, floor to ceiling. Likely above drop ceiling as well, but ceiling tiles not stained/wet. No visible growth. Also, damage to drywall (missing or bubbling paint) on wall and under windows indicating historical water intrusion, but generally not wet at time of assessment. Wet on south side of east window, near exit door. Gutter located on exterior of North wall, may be cause of water intrusion, but need to investigate further as soon as wall is removed.

Corrective Actions to be Completed by Site Based Staff

Corrective Actions to be Completed by Site Based Stair		
▼		
▼		
▼		
▼		
▼		
▼		
▼		
▼		

Corrective Actions to be Completed by PPO

Corrective Actions to be completed by 11 G	
Remove and replace wall material as needed	▼
Evaluate and repair cause of water damaged	▼
wall material (H010034)	▼
Clean entire HVAC system, inside unit	▼
	▼
	▼
	▼
	▼

Evaluation Date

Cypress Bay High

November 16, 2017

Time of Day

9:55 AM

Outdoor Conditions Temp	perature 78.9 Relativ	e Humidity 58.8	Ambient CO2 4	29
Fish Temperature 74.1	Range Relative Humidity 72 - 78 58.1 30	Range CC 9% - 60%		ccupants 1
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' X 4' Lay in	No	No		
Walls Drywall	No	Yes	entire S wall wet	
Floor 12" x 12" Vinyl	No	No		
Ceiling Clean Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	No
Walls Clean Yes	Inside of Supply		Inside of Return	
Flooring Clean Yes	Duct Clean	Yes	Duct Clean	No
Room Surfaces No Clean	Ceiling at Supply Grills Clean	Yes		
Trash Removed Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps Wet	N/A		
Room Cluttered No	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners in Room	No
Mechanical Equipment Location	on Bard like HVAC system in cla	assroom	Mechanical Room Clean	N/A
Filters Installed Properly	Yes Filters Clean	No	Inside of HVAC Unit Clean	No
Condensate Pan Clean	N/A Cooling Coil Clean	Yes		
Fresh Air Intake Location	Behind Bard unit/Exterior wa	ill 🔻	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air			oi Obstituction	

Observations

Intake

Entire South Wall is wet, floor to ceiling. Likely above drop ceiling as well, but ceiling tiles not stained/wet. Small area of suspect visible mold present on wall near floor (behind baseboard). Small cracks in the stucco at the roof, may be cause of water intrusion, but need to investigate further as soon as wall is removed.

Three work orders called in since 2015 to repair this issue. J701182, J769916, J815827. Needs to be addressed ASAP. Recommended Teacher be relocated until repair is completed.

Corrective Actions to be Completed by Site Based Staff

laii
▼
▼
▼
▼
▼
▼
▼
▼

Corrective Actions to be Completed by PPO

Corrective Actions to be completed by 11 O		
Remove and replace wall material as needed		
Evaluate and repair cause of water damaged	▶	
wall material	lacksquare	
Clean entire HVAC system, inside unit	▶	
	▶	
	•	
	▼	
	▼	