

Report: PPO

**DEERFIELD BEACH HIGH**

Walkthrough Date: 06/04/2007    Temp    RH    CO2

Outdoor Parameters:    ~~71.6~~    ~~49.4~~    ~~2032~~

Room	Priority	Responsible	Answer	Recommendation
180	Inside Parameters:	Temp 72.6	RH 49.4	CO2 2032
2	PPO	CO2 level was slightly elevated at the time of the assessment.		Physical Plant Operations to evaluate and repair as appropriate.
182	Inside Parameters:	Temp 71.4	RH 51.9	CO2 2109
2	PPO	CO2 level was slightly elevated at the time of the assessment.		Physical Plant Operations to evaluate and repair as appropriate.
236	Inside Parameters:	Temp 66.5	RH 63	CO2 1267
2	PPO	Environmental parameters were not within acceptable range at the time of assessment.		
242	Inside Parameters:	Temp 67.4	RH 62.5	CO2 1185
2	PPO	Environmental parameters were not within acceptable range at the time of assessment..		
252	Inside Parameters:	Temp 67.3	RH 64.5	CO2 1048
2	PPO	Ceiling tiles damaged or stained and require cut.		Physical Plant Operations to replace ceiling tiles as appropriate.
1	PPO	Odor detected and microbial growth identified on books.		Remove books and thoroughly clean classroom.
Room	Priority	Responsible	Answer	Recommendation

911	Inside Parameters:	Temp	RH	CO2
		65.9	57	718

2	PPO	Pests observed at the time of assessment.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
1	PPO	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
------	----------	-------------	--------	----------------

914	Inside Parameters:	Temp	RH	CO2
		69.8	50.4	688

2	PPO	Two rusted supply registers and one missing.	Physical Plant Operations to evaluate and repair as appropriate.
---	-----	--	--