

Temp 77.4 RH 55.1 CO2 463

FISH	Answer	Recommendation
148	Two broken supply/return grills.	Physical Plant Operations to evaluate and repair as appropriate.
	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
307	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
	Signs of water intrusion. Leak under sink.	Physical Plant Operations to evaluate and repair as appropriate.
601	Pests observed at the time of the assessment. Ants on ceiling.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
900	Musty odor emanating from carpet.	Physical Plant Operations to evaluate carpet and make recommendations for cleaning.
906	Cabinet under sink is damaged.	Physical Plant Operations to evaluate and repair as appropriate.
910	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
943	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
952	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
953	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.