

Report: PPO

STONEMAN DOUGLAS HIGH

Walkthrough Date: 03/30/2007 Temp RH CO2

Outdoor Parameters: 78.6 53.6 562

Room	Priority	Responsible	Answer	Recommendation
R1A	Inside Parameters:	Temp	RH	CO2
		73.4	56.5	543

2 PPO Pests observed at the time of assessment. Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.

Room	Priority	Responsible	Answer	Recommendation
087C	Inside Parameters:	Temp	RH	CO2
		73.9	46.9	1676

2 PPO Gaps in windows identified at the time of assessment. Physical Plant Operations to evaluate and repair as appropriate.

3 PPO Windows are not operable. Open doors and windows allow humid untreated air into occupied environment. Physical Plant Operations to evaluate and repair as appropriate. However site based administration to encourage staff to keep doors and windows closed.

Room	Priority	Responsible	Answer	Recommendation
401	Inside Parameters:	Temp	RH	CO2
		73	52	1377

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
535	Inside Parameters:	Temp	RH	CO2
		74.4	53.9	944

2 PPO Bathroom exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
933	Inside Parameters:	Temp	RH	CO2

		72.2	48.9	717
1	PPO	Signs of water intrusion. Leak identified.		Physical Plant Operations to evaluate for leaks and repair as appropriate.