

managing risk with responsibility

Aston A. Henry, Supervisor	
Risk Management Departmen	t

Telephone: 754 321-1900 Fax:

754 321-1917

November 20, 2	2012	Signature on File	For Custodial Supervisor Use Only	<u>r</u>
TO:	David Jones, Principal Western High School		Custodial Issues Addressed Custodial Issues Not Addressed	
FROM:	Richard Rosa, Project M Facilities Design and Co	0		
SUBJECT:	Indoor Air Quality (IAG	Q) Assessment		

On November 14, 2012, I conducted an assessment at Western High School. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

Directors, School Performance & Accountability cc: Shelley Meloni, Executive Director, Facilities Design and Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Supervisor, Risk Management Sonja Coley, Senior Project Manager, Facilities Design and Construction Broward Teachers Union Federation of Public Employees

RR/tc Enc.

	IAQ Assessn	nent		
W	Vestern High Evaluation Date	e November 14, 2012	2 Time of Day 1	2:30
Outdoor Conditions Tempera	ature 88.1 Relative	Humidity 52.9	Ambient CO2 4	16
		Range CO ² % - 60% 952		ccupants
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling Drywall Walls Ceramic Tile Floor Quarry Tile	No No No No	No No No		
Ceiling CleanYesWalls CleanYesFlooring CleanYesRoom SurfacesYesCleanYes	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	No Yes No	HVAC Return Grills Clean Inside of Return Duct Clean	No Yes
Trash RemovedYesSigns of PestsNoRoom ClutteredNo	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	N/A N/A N/A	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No No
Mechanical Equipment Location Filters Installed Properly N/A Condensate Pan Clean N/A	A Filters Clean	N/A N/A	Mechanical Room Clean Inside of HVAC Unit Clean	N/A N/A
Fresh Air Intake Location Pollutant Sources Near Air Intake	Not accessible Not readily accessible	▼	Fresh Air Intake Free of Obstruction	N/A
Observations				
The assessed space is the vestibule entering the restroom area. The HFSP states the HVAC system feeding the kitchen area is new. I recommend that the PPO HVAC department evaluate the system for normal operation due to elevated humidity.				

Corrective Actions to be Completed by Site Based Staff

Clean dust and debris from ceilings	▼
Clean HVAC supply grills with Wexcide	▼
	▼
	▼
	▼
	▼
	▼
	▼

Repair HVAC to reduce humidity level

	IAQ Ass	sessment		
	Western High Evaluation	on Date November 14, 201	12 Time of Day 12	:00
Outdoor Conditions Tem	perature 88.1 Re	elative Humidity 52.9	Ambient CO2 41	6
FishTemperature403B74.4	RangeRelative Humidit72 - 7862.7	y Range Co 30% - 60% 96		cupants
Noticeable Odor No	Visible water damag staining?	growth?	Amount of material affected	
Ceiling 2' x 4' Walls Drywall/Ceramic t	ile Yes	Yes	< 1 sq ft 10 sq ft	
Floor Quarry Tile	No No	No		
Ceiling Clean No Walls Clean No	HVAC Supply Grills Clean	Νο	HVAC Return Grills Clean	N/a
Flooring Clean Yes	Inside of Sup Duct Clean	pply N/A	Inside of Return Duct Clean	N/A
Room Surfaces Yes Clean	Ceiling at Su Grills Clean	pply No		
Trash Removed Yes	Exhaust Fans Wor		Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps		Air Fresheners	No
Room Cluttered Yes	Food if Stored in Roo in Sealed Containers		in Room	
Mechanical Equipment Locat	ion Not readily accessible		Mechanical Room Clean	N/A
Filters Installed Properly	N/A Filters Cl	ean N/A	Inside of HVAC Unit Clean	N/A
Condensate Pan Clean	N/A Cooling Coil C	lean N/A		
Fresh Air Intake Location	Not accessible	▼	Fresh Air Intake Free	N/A
Pollutant Sources Near Air Intake	Not readily accessible	▼	of Obstruction	

Observations

The assessed space is a kitchen mop room. The HFSP states the HVAC system feeding the kitchen area is new. I recommend that the PPO HVAC department evaluate the system for normal operation due to elevated humidity. The vent in the room may be an exhaust fan or the return, if an exhaust fan, check controls for proper operation. In the area of the mop sink, the grout is missing in many areas and the water intrusion to the adjoining room is coming from this location. Evaluate wall from both sides and repair as necessary. Schedule with the kitchen manager for opening of adjoining room due to the contents in room 403C storage room.

Corrective Actions to be Completed by Site Based Staff

Wipe ceiling stain w/wexcide and monitor	▼
Wipe down wall stain and monitor	▼
Clean HVAC supply grills with Wexcide	▼
	▼
	▼
	▼
	▼
	▼

Repair HVAC to reduce humidity level	▼
Evaluate and repair cause of water damage	▼
to wall material	▼
Remove and replace wall material as necessary	▼
	▼
See observations for additional info	▼
	▼
	▼

	IAQ Assessi	ment		
W	Vestern High Evaluation Dat	November 14, 201	2 Time of Day 1	2:30
Outdoor Conditions Temper	ature 88.1 Relative	Humidity 52.9	Ambient CO2 4	16
		Range CC % - 60% 103		ccupants
Noticeable OdorNoCeiling2' x 4'WallsDrywallFloor12" x 12" Vinyl	Visible water damage / staining? No Yes No	Visible microbial growth? No No No	Amount of material affected minor stains above drop	ceiling
Ceiling CleanYesWalls CleanNoFlooring CleanYesRoom SurfacesNoCleanYes	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	No Yes Yes	HVAC Return Grills Clean Inside of Return Duct Clean	No Yes
Trash RemovedYesSigns of PestsYesRoom ClutteredYes	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	N/A N/A N/A	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No No
Mechanical Equipment Location Filters Installed Properly N/A Condensate Pan Clean N/A		N/A N/A	Mechanical Room Clean Inside of HVAC Unit Clean	N/A N/A
Fresh Air Intake Location Pollutant Sources Near Air Intake	Not accessible Not readily accessible	▼ ▼	Fresh Air Intake Free of Obstruction	N/A
Observations				
The assessed space is the kitchen manager's ream. The HESP states the HVAC system feeding the kitchen area is				

The assessed space is the kitchen manager's room. The HFSP states the HVAC system feeding the kitchen area is new. I recommend that the PPO HVAC department evaluate the system for normal operation due to elevated humidity. PPO has an ongoing process in the eradication of rats in the kitchen manager's office and her storerooms. Evaluate the wall staining on the North wall appears to be coming from above the drop ceiling.

Corrective Actions to be Completed by Site Based Staff

▼
▼
▼
▼
▼
▼
▼
▼

Repair HVAC to reduce humidity level	▼
Evaluate and repair cause of staining on wall	▼
	▼
	▼
See observations for additional info	▼
	▼
	▼
	▼

IAQ Assessment	
Western High Evaluation Date November 14, 2012	2 Time of Day 12:30
Outdoor Conditions Temperature 88.1 Relative Humidity 52.9	Ambient CO2 416
FishTemperatureRangeRelative HumidityRangeCO408C70.772 - 7870.130% - 60%991	
Noticeable OdorNoVisible water damage / staining?Visible microbial growth?Ceiling2' x 4'NoNoWallsDrywallNoNoFloorQuarry TileNoNo	Amount of material affected
Ceiling CleanNoHVAC Supply Grills CleanN/aWalls CleanNoInside of Supply Duct CleanN/AFlooring CleanYesCeiling at Supply Grills CleanN/A	HVAC Return Grills Clean N/a Inside of Return Duct Clean N/A
Trash RemovedYesExhaust Fans WorkingYesSigns of PestsNoDrain Traps WetN/ARoom ClutteredNoFood if Stored in Room is in Sealed ContainersN/A	Unapproved Chemicals / Cleaners in Room No Air Fresheners No in Room
Mechanical Equipment Location Not readily accessible Filters Installed Properly N/A Filters Clean N/A Condensate Pan Clean N/A Cooling Coil Clean N/A	Mechanical Room Clean N/A Inside of HVAC Unit Clean N/A
Fresh Air Intake Location Not accessible ▼ Pollutant Sources Near Air Intake Not readily accessible ▼ Observations	Fresh Air Intake Free N/A of Obstruction

The assessed space is the women's restroom. The HFSP states the HVAC system feeding the kitchen area is new. I recommend that the PPO HVAC department evaluate the system for normal operation due to elevated humidity and low temperature. There is microbial growth around the exhaust fan and on the wall adjacent to the exhaust fan. The walls need a good wipe down. Evaluate the exhaust fan for proper HVAC control operation.

Corrective Actions to be Completed by Site Based Staff

	▼
	▼
	▼
	▼
	▼
Clean restroom exhaust fan grill w/wexcide	▼
Wipe down stains and dust from walls and monitor	▼
Wipe ceiling stain w/wexcide and monitor	▼

• • •	
Repair HVAC to reduce humidity level	▼
Set temperature to 72 - 78 degrees	▼
Evaluate for normal function of exhaust fan	▼
	▼
	▼
	▼
	▼
	▼

Western High Evaluation Date November 14, 2012 Time of Day 12:30	
Outdoor Conditions Temperature 88.1 Relative Humidity 52.9 Ambient CO2 416	
FishTemperatureRangeRelative HumidityRangeCO2Range# OccupStorage71.772 - 7869.630% - 60%1029MAX 700 > Ambient	ants
Noticeable Odor No Visible water damage / staining? Visible microbial growth? Amount of material affected Ceiling 2' x 4' No No	
Walls Drywall Yes No	
Floor 12" x 12" Vinyl No No	
Walls Clean No	10
Flooring Clean Yes Inside of Supply N/A Inside of Return Ves Duct Clean Ves Duct Clean Yes	es
Room Surfaces No Ceiling at Supply Grills Clean Yes	
	lo
Signs of Pests Yes Drain Traps Wet N/A Room Cluttered Yes Food if Stored in Room is in Sealed Containers N/A	10
Mechanical Equipment Location Not readily accessible Mechanical Room Clean N	/A
Filters Installed Properly N/A Filters Clean N/A Inside of HVAC Unit Clean	/A
Condensate Pan Clean N/A Cooling Coil Clean N/A	
Fresh Air Intake Location Not accessible ▼ Fresh Air Intake Free of Obstruction	/A
Pollutant Sources Near Air Not readily accessible Intake Intake<td></td>	

Observations

The assessed space is a storage room located in the kitchen manager's office (403C). The HFSP states the HVAC system feeding the kitchen area is new. I recommend that the PPO HVAC department evaluate the system for normal operation due to elevated humidity. PPO has an ongoing process in the eradication of rats in the kitchen manager's office and her storerooms. Evaluate wall from both sides and repair as necessary. The wall staining is located at floor level under built in desk top. Schedule with the kitchen manager for opening of this room due to the contents.

Corrective Actions to be Completed by Site Based Staff

Thoroughly clean horizontal surfaces	▼
Clean HVAC supply and return grills with Wexcide	▼
	▼
	▼
	▼
	▼
	▼
	▼

Repair HVAC to reduce humidity level	▼
Evaluate and repair cause of water damage	▼
to wall material	▼
Remove and replace wall material as necessary	▼
	▼
See observations for additional info	▼
	▼
	▼