

Report: *Site***ATTUCKS MIDDLE****Walkthrough Date: 03/30/2007 Temp RH CO2****Outdoor Parameters: 67.8 59.0 620**

Room	Priority	Responsible	Answer	Recommendation
234	Inside Parameters:	Temp	RH	CO2
		67.8	59.0	620

2 Site Temperature was low at the time of assessment.

Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.

Room	Priority	Responsible	Answer	Recommendation
290	Inside Parameters:	Temp	RH	CO2
		67.7	62.5	647

2 Site Temperature was low at the time of assessment.

Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.

2 Site Temperature was low at the time of assessment.

Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.

Room	Priority	Responsible	Answer	Recommendation
304	Inside Parameters:	Temp	RH	CO2
		68.2	60.2	691

2 Site Water is not poured down floor drain at least once a week. Site based administration should address maintenance of sinks toilets and drains with facility serviceperson staff.

1 Site No leaks or signs of water intrusion identified. Room is a science classroom and sink is being utilized as a file cabinet. Ensure that water is run in sinks at least once a week.