Indian Ridge Middle TfS IAQ Walkthrough 4-23-2008

Temp 81.7 RH 40.7 CO2 489

FISH	Answer	Recommendation
118	CO2 level was slightly elevated at the time of the	Physical Plant Operations to evaluate and repair as
	assessment.	appropriate.
119	CO2 level was slightly elevated at the time of the	Physical Plant Operations to evaluate and repair as
	assessment.	appropriate.
140	CO2 level was slightly elevated at the time of the	Physical Plant Operations to evaluate and repair as
	assessment.	appropriate.
142	CO2 level was slightly elevated at the time of the	Physical Plant Operations to evaluate and repair as
	assessment.	appropriate.
149	CO2 level was slightly elevated at the time of the	Physical Plant Operations to evaluate and repair as
	assessment.	appropriate.
154	Dripping faucet - sink on South side of room.	Physical Plant Operations to evaluate and repair as
		appropriate.
159	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks
		and repair as appropriate and replace ceiling tiles
		as appropriate.
170	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks
		and repair as appropriate and replace ceiling tiles
		as appropriate.
177	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks
		and repair as appropriate and replace ceiling tiles
		as appropriate.
192	Humidity was slightly elevated at the time of	Physical Plant Operations to evaluate HVAC
	assessment.	system for proper operation and repair as
		appropriate to lower humidity level.
213	CO2 level was slightly elevated at the time of the	Physical Plant Operations to evaluate and repair as
222	assessment.	appropriate.
223	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks
		and repair as appropriate and replace ceiling tiles
270	Giana afanatan internala Guita I di di	as appropriate.
270	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks
		and repair as appropriate and replace ceiling tiles
401	Hymidian was alightly alguated at the time of	as appropriate.
401	Humidity was slightly elevated at the time of	Physical Plant Operations to evaluate HVAC
	assessment.	system for proper operation and repair as
504	CO2 level was alightly algorated at the time of the	appropriate to lower humidity level.
504	CO2 level was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as
566C		appropriate.
300C	Areas of flooring damaged.	Physical Plant Operations to evaluate and repair as appropriate.
858C	Gans around stand along as unit identified at the time	** *
0300	Gaps around stand alone ac unit identified at the time of assessment.	·
	oi assessineit.	appropriate.