

Aston A. Henry, Supervisor Risk Management Department

# managing risk with responsibility

 Telephone:
 754 321-1900

 Fax:
 754 321-1917

October 2, 2009	Signature on File	For Custo
TO:	Mr. Washington Collado, Principal <b>Lyons Creek Middle School</b>	Custoo
FROM:	Edward See, Project Manager Risk Management Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment Portable OP112	

For Custodial Supervisor Use Only						
	Custodial Issues Addressed					
	Custodial Issues Not Addressed					
	-					

On September 25, 2009, I conducted an assessment of Portable QP112 at Lyons Creek Middle School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc:	Sharon Airaghi, Area Superintendent
	Jackie Haywood, Area Director
	Jeffrey S. Moquin, Executive Director, Support Operations
	Aston Henry, Supervisor, Risk Management
	Marshall Washington, Project Manager, Facilities and Construction Management
	Lynn Cavall, Broward Teachers Union
	Roy Jarrett, Federation of Public Employees
	Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
	Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
	Robert Krickovich, Coordinator, LEA, Facilities and Construction Management
ES/tc	
Enc.	

			IAQ As	sessment	Location Number	3101
	Lyc	ons Creek Middl	e School		Evaluation Requested	
Time of Day	8:30 am	]			Evaluation Date	September 25, 2009
Outdoor Condi	itions Ten	nperature	89.7	Relative Humidity	59.1 Ambi	ent CO2 391
Fish	Temperature	Range Rela	tive Humidity	Range	CO2 Ra	inge # O <u>ccupants</u>
P-QP112	65.1	72 - 78	62.9	30% - 60%	461 Max 70	0 > Ambient 2
Noticeable Od	lor No		Visible water nage / staining	Visible microl ? growth?	bial Amount material affe	
Ceiling Type	2 x 4 Lay	In	No	No		None
Wall Type	Tackabl	e	Yes	No	@ 4	square feet
Flooring	12 x 12 Vi	nyl	No	No		None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action F	Required
Ceiling	Yes	No	No			
Walls	No	Yes	Yes		PPO evaluate	)
Flooring	No	Yes	Yes		PPO evaluate	<b>;</b>
HVAC Supply	Grills Yes	Νο	No			
HVAC Return	Grills Yes	No	No			
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom Yes	No	No			

## Observations

#### Findings:

- Temperature was low and humidity was slightly elevated. Temperature was adjusted at the time of the assessment. Visible condensation on A/C grills and light fixtures.

- Water stain on North door and East wall

- 6 floor tiles buckled

- Non-approved chemicals in room - air freshener. Removed during the assessment.

#### **Recommendations:**

#### Site Based Maintenance:

- Ensure that non-approved chemicals are not being used in rooms (air fresheners, etc.)

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Physical Plant Operation:

- Evaluate for cause of staining on North door and East wall and repair as appropriate. Repair/replace wall material as necessary.

- Evaluate for cause of buckling floor tiles and repair as appropriate. Repair/replace floor tiles as necessary.