

Temp 78.3 RH 75.8 CO2 421

FISH	Answer	Recommendation
104D	No visible condensation at the time of assessment. Signs of previous water intrusion as evidenced by stains on walls.	Physical Plant Operations to evaluate and repair as appropriate.
113A	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
117B	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
119B	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
120	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
129	Broken HVAC supply vent over teachers desk.	Physical Plant Operations to evaluate and repair as appropriate.
131	Broken HVAC supply vent over teachers desk.	Physical Plant Operations to evaluate and repair as appropriate.
217C	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
217D	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
251	CO2 level was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
252	CO2 level was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
256	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
314	Carpet was stained torn rippled or buckled.	Physical Plant Operations to evaluate and repair/replace as appropriate.
315	Carpet was stained torn rippled or buckled.	Physical Plant Operations to evaluate and repair/replace as appropriate.
325	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
401	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.

Temp 78.3 RH 75.8 CO2 421

403	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
404	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
406	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
411	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
421	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
423	Humidity was slightly elevated at the time of the assessment.	Physical Plant Operations to evaluate and repair as appropriate.
998C	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.