

Report: PPO

MARGATE MIDDLE

Walkthrough Date: 05/18/2006 Temp RH CO2

Outdoor Parameters: 73.1 83.7 374

Room	Priority	Responsible	Answer	Recommendation
112	Inside Parameters:	Temp 72.2	RH 58.5	CO2 717

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
120A	Inside Parameters:	Temp 68.7	RH 60.8	CO2 726

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
120D	Inside Parameters:	Temp 69.4	RH 59.1	CO2 804

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.