THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

TELEPHONE (754) 321-4200

FACSIMILE: (754) 321-4285

January 5, 20	18 Signature on File	For Custodial Supervisor Use Only
TO:	Michael Consaul, Principal Pioneer Middle	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Alison Witoshynsky, Project Manager Environmental Health & Safety Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On January 4, 2018, I conducted an assessment at **Pioneer Middle School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

cc: Sam Bays, Director, Maintenance Operations Shelley Meloni, Director, Pre-Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Greg Neiman, Area Supervisor, Zone 1 Kurt Wirz, Area Manager Trades Gerald Devio, Supervisor II Custodial Benjamin Osborne, Supervisor II Custodial Mark Murray, Supervisor II Custodial Broward Teachers Union Federation of Public Employees

IAQ Assessment							
Ρ	Vioneer Middle Evaluation Date	e January 4, 2018	Time of Day 10:30 AM				
Outdoor Conditions Tempe	erature 58.4 Relative	Humidity 40.3	Ambient CO2 389				
		Range CO ² % - 60% 401	Range# OccupantsMAX 700 >0Ambient0				
Noticeable OdorNoCeiling2' X 4' Lay inWallsPlaster	Visible water damage / staining? Yes Yes	Visible microbial growth? No No	Amount of material affected 9 cut ceiling tiles (West Wall)				
Floor 12" x 12" Vinyl	No	No					
Ceiling CleanYesWalls CleanYesFlooring CleanYesRoom SurfacesNoCleanYes	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	Yes Yes No	HVAC Return Grills Clean No Inside of Return Duct Clean No				
Trash RemovedYesSigns of PestsNoRoom ClutteredNo	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	N/A Yes Yes	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room				
Mechanical Equipment Location Filters Installed Properly Y Condensate Pan Clean	n FISH 184 es Filters Clean Cooling Coil Clean	No N/A	Mechanical Room Clean No Inside of HVAC Unit Clean N/A				
Fresh Air Intake Location Pollutant Sources Near Air Intake	Roof top Not readily accessible	▼	Fresh Air Intake Free N/A of Obstruction				

Observations

Reported roof leak in SW corner/west wall; JW38763 (working). Damage to plaster wall in SW corner of room. Multiple stained ceiling tiles @ west wall, cuts needed. Wood on top of shelving looks water damaged; needs to be removed/replaced. Elevated and horizontal surfaces have a light dust layer. Dusty on CT around supply grills. Interior of mechanical room dusty on all surfaces and filter boxes stored are stained. Adjacent rooms FISH 181A/B; (A) is utilized for book storage and is cluttered with misc. paper products/projects; (B) is office/break room with a very stained/worn carpet and lots of items/clutter throughout.

Corrective Actions to be Completed by Site Based Staff

Clean dust from ceiling tiles or replace			
Thoroughly clean elevated & horizontal surfaces			
Remove and replace A/C Filters	▼		
Date filters when replaced	▼		
Clean surfaces in mechanical room	▼		
Remove storage from room (184)	▼		
Encourage occupant to reduce clutter (181A/B)	▼		
	▼		

Corrective Actions to be Completed by PPO

Clean HVAC return grills and drops		
Evaluate and repair cause of stained ceiling tile		
Install new ceiling tile upon repair, cuts needed	▼	
Remove and replace wall material as needed		
	▼	
	▼	
	▼	
	▼	