

Report: PPO

RAMBLEWOOD MIDDLE

Walkthrough Date: 03/14/2007 Temp RH CO2

Outdoor Parameters: 81.5 49.5 405

Room	Priority	Responsible	Answer	Recommendation
101	Inside Parameters:	Temp 71.7	RH 51.1	CO2 694

2 PPO Carpet was stained torn rippled or buckled. Physical Plant Operations to evaluate and repair/replace as appropriate.

Room	Priority	Responsible	Answer	Recommendation
102	Inside Parameters:	Temp 72.1	RH 51.6	CO2 758

2 PPO Carpet is severely stained. Occupants complaining of odor from carpet. Physical Plant Operations to evaluate carpeting in all admin offices.

Room	Priority	Responsible	Answer	Recommendation
103	Inside Parameters:	Temp 70.3	RH 51.1	CO2 590

2 PPO Carpet was stained torn rippled or buckled. Physical Plant Operations to evaluate and repair/replace as appropriate.

Room	Priority	Responsible	Answer	Recommendation
150	Inside Parameters:	Temp 74.7	RH 50.2	CO2 1080

2 PPO Exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
163	Inside Parameters:	Temp 69.3	RH 56.1	CO2 878

2 PPO Gaps in doors identified at the time of assessment. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
178	Inside Parameters:	Temp	RH	CO2
		69.3	50.4	1192

2 PPO Environmental parameters were not within acceptable range at the time of assessment. CO2 level was elevated. Physical Plant Operations to evaluate and repair as appropriate to lower CO2 level.

Room	Priority	Responsible	Answer	Recommendation
201	Inside Parameters:	Temp	RH	CO2
		72.4	54.9	1460

2 PPO Environmental parameters were not within acceptable range at the time of assessment. CO2 level was elevated. Physical Plant Operations to evaluate and repair as appropriate to lower CO2 level.

Room	Priority	Responsible	Answer	Recommendation
203	Inside Parameters:	Temp	RH	CO2
		73	47.5	1497

2 PPO Environmental parameters were not within acceptable range at the time of assessment. CO2 level was elevated. Physical Plant Operations to evaluate and repair as appropriate to lower CO2 level.

Room	Priority	Responsible	Answer	Recommendation
243	Inside Parameters:	Temp	RH	CO2
		74.5	41.8	1522

2 PPO Gaps in doors identified at the time of assessment. Physical Plant Operations to evaluate and repair as appropriate.

2 PPO Environmental parameters were not within acceptable range at the time of assessment. CO2 level was elevated. Physical Plant Operations to evaluate and repair as appropriate to lower CO2 level.

Room	Priority	Responsible	Answer	Recommendation
401	Inside Parameters:	Temp	RH	CO2
		72.5	55.1	1411

2 PPO There does not appear to be a dusting issue within this room. CO2 level was elevated. Physical Plant Operations to evaluate and repair as appropriate to lower CO2 level.

Room	Priority	Responsible	Answer	Recommendation

403	Inside Parameters:	Temp	RH	CO2
		73.5	57.7	1598

2 PPO There does not appear to be a dusting issue within this room. CO level was elevated. Physical Plant Operations to evaluate and repair as appropriate to lower CO2 level.

Room	Priority	Responsible	Answer	Recommendation
405	Inside Parameters:	Temp	RH	CO2
		73.3	54.3	1306

2 PPO Environmental parameters were not within acceptable range at the time of assessment.. CO2 leve was elevated. Physical Plant Operations to evaluate and repair as appropriate to lower CO2 level.

Room	Priority	Responsible	Answer	Recommendation
407	Inside Parameters:	Temp	RH	CO2
		70.4	48.5	1308

2 PPO No pests observed at the time of assessment. CO2 level was elevated. Physical Plant Operations to evaluate and repair as appropriate to lower CO2 level.

Room	Priority	Responsible	Answer	Recommendation
409	Inside Parameters:	Temp	RH	CO2
		71.5	58.4	1182

2 PPO Temperature was acceptable at time of assessment. CO2 level was elevated. Physical Plant Operations to evaluate and repair as appropriate to lower CO2 level.

Room	Priority	Responsible	Answer	Recommendation
412	Inside Parameters:	Temp	RH	CO2
		73.8	43.9	1264

2 PPO There does not appear to be a dusting issue within this room. CO2 level was elevated. Physical Plant Operations to evaluate and repair as appropriate to lower CO2 level.

Room	Priority	Responsible	Answer	Recommendation
417	Inside Parameters:	Temp	RH	CO2
		72.6	47.8	1143

Environmental parameters were not within acceptable range at Physical Plant Operations to evaluate and repair as

2 PPO the time of assessment. CO2 level was elevated. appropriate to lower CO2 level.