## WESTPINE MIDDLE

Walkthrough Date: 03/21/2007 RH **CO2 Temp Outdoor Parameters:** 71.4 **786** 60.8

Room	Priority	Responsible	Answer	Recommendation
302	Inside Parameters:	Temp	RH	CO2
		71.4	60.8	786
	1	PPO	Signs of water intrusion. Staining on wall	Physical Plant Operations to evaluate for leaks and repair as appropriate and repair wall material as appropriate.
Room	Priority	Responsible	Answer	Recommendation
416D	Inside Parameters:	Temp	RH	CO2
		71.5	62.9	696
	2	PPO	Minor rust on ceiling grids at supply grill.	Physical Plant Operations to evaluate and repair as appropriate.
Room	Priority	Responsible	Answer	Recommendation
<b>Room</b> 715	Inside Parameters:	Temp	RH RH	Recommendation CO2
	Inside Parameters:	Temp		
	Inside Parameters:	Temp 68.7	RH	CO2
715	Inside Parameters:	Temp 68.7	RH 62.7 Signs of water intrusion. Stained ceiling tiles.	CO2  1640  Physical Plant Operations to evaluate for leaks and repair as
715	Inside Parameters:	Temp 68.7 PPO	RH 62.7 Signs of water intrusion. Stained ceiling tiles.	CO2  1640  Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
715 Room	Inside Parameters:  1 Priority Inside Parameters:	Temp 68.7 PPO Responsible Temp	RH 62.7 Signs of water intrusion. Stained ceiling tiles.  Answer  RH	CO2  1640  Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.  Recommendation

acceptable range at the time of assessment..