Document:

Progress report for hurricane damaged portables at Flanagan HS prepared contemporaneously by SBBC Portables Department project manager.

Action:

- The project manager visited Flanagan HS on 2/24/06 and reported the status of twenty (20) portable unit #'s (1176VE, 1187VE, 1260AP, 1189VE, 005L, 1188VE, 008L, 009L, 1180VE, 1271CP, 1183VE, 1199VE, 1181VE, 1171CA, 010L, 580C, 324, 651C, 145N, and 32N).
- 2. The project manager visited Flanagan HS on 03/30/06 and reported the status of twenty (20) portable unit #'s (1176VE, 1187VE, 1260AP, 1189VE, 005L, 1188VE, 008L, 009L, 1180VE, 1271CP, 1183VE, 1199VE, 1181VE, 1171CA, 010L, 580C, 324, 651C, 145N, and 32N).

Note that the same project manager conducted the visit discussed in Step 7 below.

Conclusion:

An audit of the project manager's documentation verifies that project managers were inspecting work being formed on the portable classroom units in question. The report dated 2/24/06 lists eighteen (18) portables that had been completed and indicates two (2) units are undergoing repairs on that date. The report dated 3/30/06 confirms that nineteen (19) portables had been completed to date and indicates that one (1) unit was undergoing repairs on that date.

This documentation indicates that more than two (2) units were serviced as alleged in the audit for Invoice No. 0584-25 in the "Ashbritt, Inc. Invoice Table -0584-21 thru 39" on page 20 of the audit.

0

		<u>.</u>	5	t	E	f	>	-	3													
																			Flanagan High		School Name	
32N	145N	651C	324	580C	010L	1171CA	1181VE	1199VE	1183VE	1271CP	1180VE	009L	008L	1188VE	005L	1189VE	1260AP	1187VE	1176VE		Unit #	Hurric
		X																		Grid	Ceiling Ceiling	ane Da
		X																		Tiles	Ceiling	amage
		×																		Insulation	Ceiling	Hurricane Damaged Portables, Scope of Work
		×																		Fixtures	Light	les, Scol
×		×																		Walls	Interior	be of V
×		×																		Walls Insulation	Wall	/ork
																				Siding	Exterior	
																				flooring	Sub	Dat
		×																		Siding flooring Floor Tile Alarm	Vinyl	Date: 02/24/06
																				Alarm	Fire	90
** See Below**	Complete	GUTTED	Complete		Comments																	

***32N walls half way up drywall installed, needs mud. ***

(2)

Complete											32N	
Complete											145N	
See Below		×			×	Х	×	×	×	X	651C	
Complete											324	
Complete											580C	
Complete										. 1	010L	
Complete										,	1171CA	
Complete										,	1181VE.	
Complete											1199VE	
Complete										,	1183VE	
Complete											1271CP.	
Complete										,	1180VE	
Complete											009L	
Complete										/	008L	
Complete										1	1188VE	
Complete										. ,	005L	
Complete										1	1189VE	
Complete										,	1260AP	
Complete										/	1187VE	
Complete										1	1176VE	Flanagan High
	Alarm	flooring Floor Tile	flooring	Siding	Insulation	Walls	Fixtures	Insulation Fixtures	Tiles	Grid		
Comments	Fire	Vinyl	Sub	Exterior	Wall	Interior	Light	Ceiling	Ceiling	Ceiling Ceiling	Unit #	School Name
,	/06	Date: 03/30/06	Da		Nork	pe of \	les, Scc	Hurricane Damaged Portables, Scope of Work	amage	cane D	Hurrio	

^{***651}C Still incomplete, walls complete, but still no ceiling, or lights after 6 weeks***