

## managing risk with responsibility

Aston A. Henry, Director Risk Management Department Telephone: 754 321-1900 Fax: 754 321-1917

D 1 4	C 2014	194
December 16	5, 2014 Signature on 1	For Custodial Supervisor Use Only
TO:	Roy Norton, Manager Physical Plant Operations	Custodial Issues Addressed  Custodial Issues Not Addressed
FROM:	Robert Krickovich, Coordinator I, LEA Risk Management Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On November 20, 2014, I conducted an assessment at **Rock Island Annex - Administration.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Aston Henry, Director, Risk Management
Sonja Coley, Senior Project Manager, Facilities & Construction
Broward Teachers Union
Federation of Public Employees

RK/tc Enc.

Clean Mechanical room	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼

Evaluate and repair cause of stained ceiling tile	
Replace water damaged carpet with vinyl tile	
	▼
	▼
	▼
	▼
	▼
	▼

Outdoor Conditions Tem	nperature 80.7 Relat	tive Humidity 58.4	Ambient CO2	
Fish         Temperature           116         73.7	Range Relative Humidity 72 - 78 44.9	Range CO 30% - 60%	Range # Oo MAX 700 > Ambient	ccupants 1
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' X 4' Lay in	Yes	No	1 tile	
Walls Drywall	Yes	No	24 sq ft	
Floor Carpet	Yes	No	10 sq ft	
Ceiling Clean Yes Walls Clean Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	N/a
Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	N/A
Room Surfaces Yes Clean	Ceiling at Suppl Grills Clean	Yes Yes		
Trash Removed Yes	Exhaust Fans Working		Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps We	et N/A	Air Fresheners	-
Room Cluttered No	Food if Stored in Room in Sealed Containers	is N/A	in Room	No
Mechanical Equipment Locat	tion FISH 119		Mechanical Room Clean	No
Filters Installed Properly	N/A Filters Clear	n N/A	Inside of HVAC Unit Clean	N/A
Condensate Pan Clean	N/A Cooling Coil Clear	n N/A		
Fresh Air Intake Location	Outside of Room	▼	Fresh Air Intake Free	Yes
Pollutant Sources Near Air Intake		▼	of Obstruction	

## **Observations**

Stained (wet) ceiling tile over door - wall is water stained under wet ceiling tile - carpet under wet ceiling tile is water damaged

Mechanical room 119 - Air intake at floor of room - floor has heavy dirt, debris, grass and leaves under HVAC Unit.

Corrective Actions to be Completed by Site Based Staff

Corrective Actions to be completed by Oile Based Otali	
Clean Mechanical room	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼

## **Corrective Actions to be Completed by PPO**

Evaluate and repair cause of stained ceiling tile	▼
Remove and replace stained ceiling tiles	▼
Evaluate and repair cause of water damaged	▼
wall material	▼
Remove and replace wall material as needed	▼
Replace water damaged carpet with vinyl tile	▼
	lacksquare
	▼