

**Title I (ECIA) Administration
TfS IAQ Walkthrough
4-29-2008**

Temp 71.7 RH 46.1 CO2 598

FISH	Answer	Recommendation
101	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
105	Excessive dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
109	Supply vents closed/blocked at the time of assessment.	Facilities serviceperson to open supply vents.
110	Slight dust accumulation was observed on environmental surfaces due to clutter at the time of assessment.	Site based administration should work with room occupant to encourage occupant to reduce clutter to assist facility serviceperson with their dusting efforts
111	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
112	Slight dust accumulation was observed on environmental surfaces due to clutter at the time of assessment.	Site based administration should work with room occupant to encourage occupant to reduce clutter to assist facility serviceperson with their dusting efforts
120	Ceiling tiles broken damaged or missing.	Facilities serviceperson to replace ceiling tiles.
	Slight dust accumulation was observed on environmental surfaces due to clutter at the time of assessment.	Site based administration should work with room occupant to encourage occupant to reduce clutter to assist facility serviceperson with their dusting efforts
	Ceiling tiles broken damaged or missing.	Facilities serviceperson to replace ceiling tiles.
126	Slight dust accumulation was observed on environmental surfaces due to clutter at the time of assessment.	Site based administration should work with room occupant to encourage occupant to reduce clutter to assist facility serviceperson with their dusting efforts
127	Stuffed animals in the room.	Site based administration to advise occupant to thoroughly clean stuffed animals or remove from the room. Stuffed animals are a source of allergens.
	Slight dust accumulation was observed on environmental surfaces due to clutter at the time of assessment.	Site based administration should work with room occupant to encourage occupant to reduce clutter to assist facility serviceperson with their dusting efforts
128	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.

**Title I (ECIA) Administration
TfS IAQ Walkthrough
4-29-2008**

Temp 71.7 RH 46.1 CO2 598

FISH	Answer	Recommendation
	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
130	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
143	Dust impaction on ceiling tiles at supply grills.	Facilities serviceperson to thoroughly clean or remove and replace ceiling tiles.
149	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
152	Live plants in room. Plant soil is a source of microbial growth.	Site based administration to advise staff to remove live plants.
	Ceiling tiles broken, damaged or missing.	Facilities serviceperson to replace ceiling tiles.
	Temperature was elevated at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.