

Aston A. Henry, Director

managing risk with responsibility

754 321-1900

Telephone:

Risk Managem	ent Department	Fax:	754 321-1917
August 8, 2013	Signature on File	For Custodia	l Supervisor Use Only
TO:	Robert Crawford, Principal Atlantic Technical Center		Issues Addressed Issues Not Addressed
FROM:	Robert Krickovich, Coordinator I, LEA Risk Management Department		
SUBJECT:	Indoor Air Quality (IAQ) Assessment	-	

On August 6, 2013, I conducted an assessment at **Atlantic Technical Center**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Director, Risk Management Sonja Coley, Senior Project Manager, Facilities & Construction Broward Teachers Union Federation of Public Employees

RK/tc Enc.

IAQ Assessment

Atlantic Technical Center Eval	aluation Date August 6, 2013 Time of Day 2:00								
Outdoor Conditions Temperature 94.1	Relative Humidity 58.7 Ambient CO2 476								
Fish Temperature Range Relative Hum 29C 79.1 72 - 78 41.1									
Noticeable Odor No Visible water da staining?									
Ceiling 2' X 4' Lay in Yes	Yes 15 stained or missing tiles								
Walls Drywall No	No								
Floor 12" x 12" Vinyl No	No								
Ceiling Clean Yes HVAC Su Grills Cle									
Flooring Clean Yes Inside of Duct Clean									
Room Surfaces Yes Ceiling a Grills Clean	at Supply lean N/a								
Trash Removed Yes Exhaust Fans	Cleaners in Room No								
Signs of Pests No Drain Ti	Traps Wet N/A Air Fresheners No								
Room Cluttered No Food if Stored in Sealed Contain	in Room is in Room								
Mechanical Equipment Location Wall Mounted Unit Mechanical Room Clean N/A									
Filters Installed Properly N/A Filter	ers Clean N/A Inside of HVAC Unit Clean N/A								
Condensate Pan Clean N/A Cooling Co	Coil Clean N/A								
Fresh Air Intake Location Outside of Unit	▼ Fresh Air Intake Free of Obstruction Yes								
Pollutant Sources Near Air Intake	▼								
Observations									
9 ceiling tiles removed due to roof leaks - 6 stained ceiling tiles - 1 ceiling tile with microbial growth over North West cabinet - 2 light fixtures with water in the lenses - insulation above ceiling is wet and sagging - some paper on the insulation above the ceiling has microbial growth									
Corrective Actions to be Completed by Site Based Staff Corrective Actions to be Completed by PPO									
Remove stained ceiling tiles	▼ Repair / replace roofing ▼								
	▼ Replace water damaged ceiling insulation ▼								
	 								
	▼								
	V V								

IAQ Assessment

Atlantic Lec	chnical Center Evaluation	August August	6, 2013	Time of Day	2:00			
Outdoor Conditions Tempe	erature 94.1 F	Relative Humidity	58.7	Ambient CO2 4	76			
	Range Relative Humid 72 - 78 43.8	ity Range 30% - 60%	CO² 469	Range # Oo MAX 700 > Ambient	2			
Noticeable Odor No	Visible water dama staining?	age / Visible mid growtl		Amount of material affected				
Ceiling 2' X 4' Lay in	Yes	Yes		15 tiles				
Walls Homasote	Yes	Yes		12 - 4' x 10' panels				
Floor 12" x 12" Vinyl	Yes	No		90Sq ft				
Ceiling Clean Yes Walls Clean Yes	HVAC Supp Grills Clean Inside of Su	Yes		HVAC Return Grills Clean Inside of Return	Yes			
Flooring Clean Yes	Duct Clean	N/A		Duct Clean	N/A			
Room Surfaces Yes Clean	Ceiling at S Grills Clean							
Trash Removed Yes	Exhaust Fans Wo			napproved Chemicals / leaners in Room	No			
Signs of Pests No Room Cluttered No	Drain Trap Food if Stored in Ro in Sealed Containe	oom is		Air Fresheners in Room	No			
Mechanical Equipment Location Wall Mounted Unit Mechanical Room Clean								
Filters Installed Properly N	/A Filters 0	Clean N/A	Insi	de of HVAC Unit Clean	N/A			
Condensate Pan Clean N	Cooling Coil (Clean N/A						
Fresh Air Intake Location Pollutant Sources Near Air	Outside of Unit		▼	Fresh Air Intake Free of Obstruction	Yes			
Intake	None							
Observations								
Water leaking from roof onto f microbial growth behind white				re removed - water st	ains and			
Corrective Actions to be Completed by Site Based Staff Corrective Actions to be Completed by PPO								
Remove stained ceiling tiles ▼ Repair / replace roofing								
	▼		Replace water damaged ceiling insulation					

▼ ▼ ▼

Repair water damaged flooring