

Jeffrey S. Moquin, Director  
Risk Management Department

Telephone: 754-321-3200  
Facsimile: 754-321-3290

July 25, 2005

TO: Mr. Michael McGinty, Principal  
**Bright Horizons Center**

FROM: Kenneth I. Partee, Project Manager, Occupational Health and Environmental  
Control  
Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment  
FISH 211A

On July 19, 2005 the IAQ Assessment Team conducted an assessment of FISH 211A at **Bright Horizons Center**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent  
Craig Anderson, Area Director  
Jeffrey S. Moquin, Director, Risk Management  
Rigo Zubizarreta, Project Manager II, Facilities and Construction Management  
LaFrances Trotter, Broward Teachers Union  
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1  
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division  
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc  
Enc.

# IAQ Assessment

Bright Horizons Center

Evaluation Requested July 18, 2005

Time of Day 9:30 am

Evaluation Date July 19, 2005

Outdoor Conditions      Temperature 90.3      Relative Humidity 62.8      Ambient CO2 464

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<span style="border: 1px solid black; padding: 2px;">211A</span>	<span style="border: 1px solid black; padding: 2px;">80.5</span>	<span style="border: 1px solid black; padding: 2px;">72 - 78</span>	<span style="border: 1px solid black; padding: 2px;">71.7</span>	<span style="border: 1px solid black; padding: 2px;">30% - 60%</span>	<span style="border: 1px solid black; padding: 2px;">486</span>	<span style="border: 1px solid black; padding: 2px;">Max 700 &gt; Ambient</span>	<span style="border: 1px solid black; padding: 2px;">0</span>
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>		<span style="border: 1px solid black; padding: 2px;">At light fixture</span>	
Ceiling Type	<span style="border: 1px solid black; padding: 2px;">Plaster</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">At light fixture</span>		
Wall Type	<span style="border: 1px solid black; padding: 2px;">Plaster</span>		<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">None</span>		
Flooring	<span style="border: 1px solid black; padding: 2px;">Concrete</span>		<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">None</span>		

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean with Wexcide disinfectant at light fixture</span>
Walls	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Replace all cabinets and shelves</span>
Flooring	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Repaint/reseal floor</span>
HVAC Supply Grills	<span style="border: 1px solid black; padding: 2px;"></span>	<span style="border: 1px solid black; padding: 2px;"></span>	<span style="border: 1px solid black; padding: 2px;"></span>	<span style="border: 1px solid black; padding: 2px;">N/A</span>
HVAC Return Grills	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean with Wexcide disinfectant</span>
Ceiling at Supply Grills	<span style="border: 1px solid black; padding: 2px;"></span>	<span style="border: 1px solid black; padding: 2px;"></span>	<span style="border: 1px solid black; padding: 2px;"></span>	<span style="border: 1px solid black; padding: 2px;">N/A</span>
Surfaces in Room	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean as appropriate</span>

## Observations

### Findings: Room described as a pool storage closet

- Custodial staff advised that roof top AHU has not worked for 6 months
- Air vent is loud
- Visible microbial growth on cabinets and shelves. Cabinets and shelves are also deteriorated.
- Visible microbial growth on ceiling near light fixture
- Visible microbial growth on swim gear
- Dust and debris on HVAC return grills
- Concrete floor needs to be painted/sealed
- Light fixture needs bulbs replaced
- Door does not close properly

### Recommendations:

#### Site Based Maintenance:

- Clean ceiling at light fixture with Wexcide disinfectant solution
- Remove/replace swim gear with microbial growth
- Clean HVAC return grills with Wexcide disinfectant solution
- Paint/seal concrete floor
- Replace bulbs in light fixture
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations Division:

- Evaluate and repair HVAC unit
- Evaluate air vent for proper operation
- Install grill in door to increase air exchange
- Evaluate cabinets and shelves and remove/replace as appropriate
- Evaluate door and repair as appropriate