

Temp 73.5 RH 56.6 CO2 313

FISH	Answer	Recommendation
128A	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
221	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
238	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
	Water damage on wall at emergency door - bottom.	Physical Plant Operations to evaluate and repair as appropriate.
	Pests observed at the time of assessment. Insect debris in kitchen cabinet.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
407G	Carpet was stained, torn, rippled or buckled.	Physical Plant Operations to evaluate and repair/replace as appropriate.