

Report: PPO

SUNSET SCHOOL

Walkthrough Date: 05/24/2006

Temp

RH

CO2

Outdoor Parameters:

77.3

52.3

514

Room	Priority	Responsible	Answer	Recommendation
101K	Inside Parameters:	Temp 72.7	RH 55.8	CO2 869

1	PPO	No visible condensation at the time of assessment. Signs of previous water intrusion as evidenced by stains on walls.	Physical Plant Operations to evaluate and repair as appropriate.
1	PPO	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.