

Report: PPO

**DAVE THOMAS EDUCATION CENTER**

Walkthrough Date: 05/11/2006 Temp RH CO2

Outdoor Parameters: 91.6 50.1 524

Room	Priority	Responsible	Answer	Recommendation
101D	Inside Parameters:	Temp	RH	CO2
		75.9	47.6	1047

2 PPO Temperature varied between 74.8 - 79.1 within a span of 4 min. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
101J	Inside Parameters:	Temp	RH	CO2
		76.5	46.1	1060

2 PPO Temperature varies. Physical Plant Operations to evaluate and repair as appropriate.

2 PPO Temperature varied between 74.3 - 77.6 within 4-5 min. Becoming warmer. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
101K	Inside Parameters:	Temp	RH	CO2
		76.6	46.9	1076

2 PPO Water is not poured down floor drain at least once a week. Open drain for dehumidifier, slight odor. Also occupant claims that the unit gets very hot. Fears it is a fire hazard. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
129	Inside Parameters:	Temp	RH	CO2
		72.1	41.4	1040

No leaks identified. Signs of previous water intrusion as evidenced

1	PPO	by staining. FISH 128C - Adjoining Kitchen for ESE adult classroom.	Physical Plant Operations to evaluate and repair as appropriate.
2	PPO	It appears that the ventilation system is not adequate based on room activities. Room is used by adult ESE students.	Replace exhaust fan, check flowrate.