## **Tools for Schools - Indoor Air Quality**

## **Follow-up Action Plan for District Maintenance**

**Whispering Pines Center** 

Walkthrough Date: 2/25/2004 Temp RH Co2 Assignment Member: Jeff Moquin

**Outside Measurements** 



Principal: Ms. Marsha Iler

| Room | Priority | Responsible          | Assessment Comments                                      | Recommended Corrective Action  |
|------|----------|----------------------|--|--|
| 320  | 1        | District Maintenance | Air handler valve leaking. Microbial growth.             | Maintenance to inspect and repair as appropriate.  |
| 405  | 2        | District Maintenance | Signs of previous water intrusion by window system.      | Maintenance to inspect and repair as appropriate.  |
| 603  | 1        | District Maintenance | Signs of water intrusion on SW wall.                     | Maintenance to inspect for leak and repair as appropriate. Also, corkboards need to be removed.                  |
| 607  | 2        | District Maintenance | Teacher advised that there are roaches in room.          | Maintenance needs to establish work order to inspect room for pests and implement appropriate corrective action. |
| P-2  | 2        | District Maintenance | Humidity slightly elevated.                              | Maintenance needs to inspect HVAC for proper operation.  |
| P-2  | 2        | District Maintenance | Temperature was slightly elevated at time of assessment. | Maintenance needs to inspect HVAC for proper operation.  |

8/19/2005 Whispering Pines Center Sorted by Room and Priority Page 1 of 1