

# Tools for Schools Phase IX - Indoor Air Quality

## Follow-up Action Plan for PPO



Beachside Montessori Village

2041

79.3 77.4 467

Walkthrough Date: 5/2/2012

Temp RH Co2

Outside Measurements

Room	Priority	Concern	Response	Recommendation
109	2	Classroom is free of significant temperature shifts?	Temperature was not within range at the time of the assessment.	Evaluate HVAC for proper operation and repair as appropriate.
109	2	Humidity is generally acceptable? (Typically too high if higher than 60% relative humidity [RH] or too low if lower than 30% RH.)	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
			<i>South Area working on ongoing A/C issues</i>	
129	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
134	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
155	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
159	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
202	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
208	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
210	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
212	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
213	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
214	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
221	2	Classroom is free of significant temperature shifts?	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.

Room	Priority	Concern	Response	Recommendation
232	2	X - Humidity	Humidity was elevated at the time of the assessment  South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.
235	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
261	2	X - Humidity	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.