## **Cresthaven Elementary**

112

114

Flooring

Flooring

**Temp** 

**Temp** 

RH

**Outdoor Parameter Measurements:** 

WalkthroughDate: 7/2/2004 **Temp** 84.9

RH75%

Co<sub>2</sub>

-	Category		Detail	Assessment Comments	Recommended Corrective Action
100	71.9	54%	240		

Co2

Health and Hygiene Education Provide information about IAQ and health. Contact EPA website www.epa.gov/iaq Health and Hygiene Education Inform students and staff about the Site based administration will provide importance of good hygiene in preventing information to site based staff. the spread of airborne contagious diseases. Health and Hygiene Education Obtain Indoor Air Quality: An introduction Site based administration will provide for health professionals. information to site based staff. 71.9 54% 180 RHCo<sub>2</sub>

Interior Inspection Restroom fans. There were no problems observed at No corrective action recommended at this time of assessment. Interior Inspection Check preventative indoor items. Live plants and stuffed animals were No corrective action recommended at this removed from the interior. time. Interior Inspection General maintenance items. There were no problems observed at No corrective action recommended at this time of assessment. 72.5 53% 170

**Temp** RHCo2

**Drain Traps** Fill drain traps in your area each week.

> Post-Installation. During installation.

There were no problems observed at time of assessment.

Not applicable. Not applicable. No corrective action recommended at this time.

Thursday, August 18, 2005 Page 1 of 10

		<b>5</b>			
	Flooring	Pre-Installation	Not applicable.		
	General Activities	Pre-Renovation.	Not applicable.		
	General Activities	During renovation.	Not applicable.		
	General Activities	Plan isolation strategy for renovation.	Not applicable.		
	General Cleanliness	Check for pests.	There were no problems observed at time of assessment.	No corrective action recommended at this time.	
	General Cleanliness	Clean spills promptly.	There were no problems observed at time of assessment.	No corrective action recommended at this time.	
	Local Exhaust Fans	Determine if activities generate air pollutants and whether the room or area is equipped with local exhaust fans.	There were no problems observed at time of assessment.	No corrective action recommended at this time.	
	Local Exhaust Fans	Confirm that local exhaust fans (if any) function properly.	There were no problems observed at time of assessment.	No corrective action recommended at this time.	
	Painting	Close-out.	Not applicable.		
	Painting	Pre-Renovation.	Not applicable.		
	Painting	During Renovation.	Not applicable.		
	Roofing	Pre-Renovation.	Not applicable.		
	Roofing	During Renovation.	Not applicable.		
	Thermal Comfort	Humidity level.	The humidity was 53% at the time of assessment. The desired humidity level is below 60%.	No corrective action recommended at this time.	
	Thermal Comfort	Check comfort factors.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.	
122	69.4	59% 310			
	Temp	RH Co2			
	Excess Moisture in Classrooms	Condensate (condensed water, or "fog") on cold surfaces.	There were no problems observed at time of assessment.	No corrective action recommended at this time.	
	General Classroom Information		Items hanging from ceiling causing gaps in surface seal.	Remove items from ceiling.	

**Assessment Comments** 

**Recommended Corrective Action** 

Detail

Category

	Category			Detail	Assessment Comments	Recommended Corrective Action
23		70.5	63%	300		
		Temp	RH	Co2		
	General Classro	oom Information			Missing ceiling tiles.	Replace ceiling tiles.
	General Cleanli	ness			Humidity slightly elevated.	Custodial staff to ensure that all windows are securely closed. If necessary, a work order should be called in.
	Ventilation		Check	for unexplained odors.	No odors were detected at time of assessment.	No corrective action recommended at this time.
125		68.5	59%	340		
		Temp	RH	Co2		
	General Classro	oom Information			Removed items that were hanging from ceiling.	No corrective action recommended at this time.
	Thermal Comfort		Humidity level.		The humidity was 59% at the time of assessment. The desired humidity level is below 60%.	No corrective action recommended at this time.
	Ventilation		Check	for unexplained odors.	No odors were detected at time of assessment.	No corrective action recommended at this time.
27		69	59%	400		
		Temp	RH	Co2		
	Health and Hyg	ene Education	importa the spi	students and staff about the ance of good hygiene in preventing read of airborne contagious		Site based administration will provide information to site based staff.
			diseas	<del>U</del> S.		

Temp	RH Co2		
Combustion Application	Viewelly in a set or bound or an end of	There were no negligate above of at	No compatitue estimates
Combustion Appliances	Visually inspect exhaust components.	There were no problems observed at time of assessment.	No corrective action recommended time.
Combustion Appliances	Check for backdrafting of combustion appliances.	There were no problems observed at time of assessment.	No corrective action recommended time.
Combustion Appliances	Note odors when first entering a location containing combustion appliances.	No odors were detected at time of assessment.	No corrective action recommended time.
Dust Control	Use proper dust wiping techniques.	Custodial staff is working on this.	No corrective action recommended time.
Dust Control	Purchase and maintain barrier floor mats for all school entrances.		School to look into purchasing thes
Dust Control	Use higher efficiency vacuum bags.		School to look into purchasing thes
Maintenance Supplies	Establish maintenance practices that minimize occupant exposure to hazardous materials.	Custodial staff will take care of this.	No corrective action recommended time.
Maintenance Supplies	Follow good safety, handling, and storage practices.	There were no problems observed at time of assessment.	No corrective action recommended time.
Maintenance Supplies	If you make purchase decisions, or recommend products for purchase, confirm that supplies are safe to use.		Site based administration will provinformation to site based staff.
Maintenance Supplies	Learn about your maintenance supplies.		Site based administration will provinformation to site based staff.
Moisture, Leaks, and Spills	Prevent moisture condensation.	There were no problems observed at time of assessment.	No corrective action recommended time.
Pest Control	Use Integrated Post Management (IPM) methods of pest control.	There were no problems observed at time of assessment.	No corrective action recommended time.
	Please get us some help!!!		
Combustion Appliances	Note odors when first entering a location containing combustion appliances.	No odors were detected at time of assessment.	No corrective action recommended time.
Combustion Appliances	Visually inspect exhaust components.	There were no problems observed at time of assessment.	No corrective action recommended time.
Combustion Appliances	Check for backdrafting of combustion appliances.	There were no problems observed at time of assessment.	No corrective action recommended time.
Drain Traps	Confirm that all drains have drain traps.	There were no problems observed at time of assessment.	No corrective action recommended time.

**Assessment Comments** 

**Recommended Corrective Action** 

Detail

430

51%

Category

70.8

130

	Dust Control		Use	proper dust wiping techniques.	Custodial staff is working on this.	No corrective action recommended at this time.
	Dust Control		vent	uum dust from heating, cooling, and illation air return grilles and air supply speriodically.	Summer cleaning is in progress.	No corrective action recommended at this time.
	Dust Control			chase and maintain barrier floor mats all school entrances.		School to look into purchasing these items.
	Floor Cleaning		Perf	orm restorative maintenance.	Summer cleaning is in progress.	No corrective action recommended at this time.
	Floor Cleaning		Gen	eral items to watch for.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Maintenance So	upplies	reco	ou make purchase decisions, or ommend products for purchase, irm that supplies are safe to use.		Site based administration will provide information to site based staff.
	Maintenance So	upplies	mini	ablish maintenance practices that mize occupant exposure to ardous materials.		Site based administration will provide information to site based staff.
	Moisture, Leaks	s, and Spills	Prev	vent moisture condensation.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Moisture, Leaks	s, and Spills		ect the building for signs of moisture, s, or spills.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Moisture, Leaks	s, and Spills	Lool	k for signs of water damage.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Moisture, Leaks	s, and Spills		pond promptly when you see signs of sture, or when leaks or spills occur.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
132		72.1	64%	260		
		Temp	RH	Co2		
	Combustion Ap	pliances		e odors when first entering a location aining combustion appliances.	No odors were detected at time of assessment.	No corrective action recommended at this time.
	Combustion Ap	pliances		ck for backdrafting of combustion liances.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Combustion Ap	pliances	Visu	ally inspect exhaust components.	Dust was seen on exhaust.	Custodial staff will take care of this.
	Drain Traps			firm that all drain traps in areas which you have access are filled.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Drain Traps		Con	firm that all drains have drain traps.	There were no problems observed at time of assessment.	No corrective action recommended at this time.

**Assessment Comments** 

**Recommended Corrective Action** 

Detail

Category

Thursday, August 18, 2005 Page 5 of 10

	Category			Detail	Assessment Comments	Recommended Corrective Action
	Dust Control		Use p	proper dust wiping techniques.	Custodial staff is working on this.	No corrective action recommended at this time.
	Floor Cleaning		Perfo	rm restorative maintenance.	Summer cleaning is in progress.	No corrective action recommended at this time.
	Floor Cleaning		Gene	ral items to watch for.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Maintenance S	upplies	recon	make purchase decisions, or nmend products for purchase, m that supplies are safe to use.		Site based administration will provide information to site based staff.
	Moisture, Leak	s, and Spills		ond promptly when you see signs of ure, or when leaks or spills occur.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Moisture, Leak	s, and Spills	Look	for signs of water damage.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Moisture, Leaks, and Spills		Inspect the building for signs of moisture, leaks, or spills.		There were no problems observed at time of assessment.	No corrective action recommended at this time.
			We can use a	nother warm body.		
134		71.6	57%	300		
		Temp	RH	Co2		
	General Cleanl	iness	Conti prope	rm that the classroom is cleaned orly	General cleanliness appeared adequate on date of assessment.	No corrective action recommended at this time.
	Thermal Comfort		Humidity level.		The humidity was 57% at the time of assessment. The desired humidity level is below 60%.	No corrective action recommended at this time.
			When the roo	m above is cooking we smell a burning	smell.	
138		73	68%	300		
		Temp	RH	Co2		
	Excess Moistur	e in Classrooms		ensate (condensed water, or "fog") ld surfaces.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	General Classr	oom Information			Humidity slightly elevated.	Custodial staff to ensure that all windows are securely closed. If necessary, a work order should be called in.
	General Classr	oom Information			Items hanging from ceiling causing gaps in seal.	Custodial staff to remove items hanging from ceiling.

	Category		Detail	Assessment Comments	Recommended Corrective Action
	General Cleanliness	Confir prope	m that the classroom is cleaned rly	General cleanliness appeared adequate on date of assessment.	No corrective action recommended at this time.
139	71.4	57%	330		
	Temp	RH	Co2		
	General Cleanliness	Confir prope	m that the classroom is cleaned rly	General cleanliness appeared adequate on date of assessment.	No corrective action recommended at this time.
40	71	64%	340		
	Temp	RH	Co2		
	Animals in the Classroom		special care with asthmatic or other ive students.	No animals in the classroom. Air fresheners were found in room.	Remove air fresheners.
	General Classroom Information			Humidity slightly elevated.	Custodial staff to ensure that all windows are securely closed. If necessary, a work order should be called in.
	General Cleanliness	Confir prope	m that the classroom is cleaned	General cleanliness appeared adequate on date of assessment.	No corrective action recommended at this time.
	General Cleanliness	Check	for pests.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
42	72.9	70%	298		
	Temp	RH	Co2		
	General Cleanliness	Confir prope	m that the classroom is cleaned rly	General cleanliness appeared adequate on date of assessment.	No corrective action recommended at this time.
	Thermal Comfort		lity level.	Humidity slightly elevated.	Custodial staff to ensure that all windows are securely closed. If necessary, a work order should be called in.

	Category			Detail	Assessment Comments	Recommended Corrective Action
203		71.9	67%	390		
		Temp	RH	Co2		
	General Classro	oom Information			Humidity slightly elevated.	Custodial staff to ensure that all windows are securely closed. If necessary, a work order should be called in.
	General Cleanliness		Check for pests.		There were no problems observed at time of assessment.	No corrective action recommended at this time.
207		71	63%	310		
		Temp	RH	Co2		
	General Classro	oom Information			Non approved appliances found in room.	Remove appliances.
	General Classro	oom Information			Humidity slightly elevated.	Custodial staff to ensure that all windows are securely closed. If necessary, a work
	General Classro	oom Information	confir	have mechanical ventilation, m that air is flowing into the room the air supply vent(s).	Air is flowing into the room from the air supply vents.	Custodial staff to ensure that all windows are securely closed. If necessary, a work order should be called in.  No corrective action recommended at this time.
208		oom Information	confir	m that air is flowing into the room	Air is flowing into the room from the air	are securely closed. If necessary, a work order should be called in.  No corrective action recommended at this
208			confir from	m that air is flowing into the room the air supply vent(s).	Air is flowing into the room from the air	are securely closed. If necessary, a work order should be called in.  No corrective action recommended at this
208		71.9 <b>Temp</b>	confir from 6	m that air is flowing into the room the air supply vent(s).	Air is flowing into the room from the air	are securely closed. If necessary, a work order should be called in.  No corrective action recommended at this

	Category	Detail	Assessment Comments	Recommended Corrective Action
221	72.3	60% 350		
	Temp	RH Co2		
	General Cleanliness	Confirm that the classroom is opposely	Cleaned General cleanliness appeared adequate on date of assessment. Stuffed animals and non SBBC chemicals were found in room.	Removed stuffed animals and chemicals.
	Local Exhaust Fans	General items.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Thermal Comfort	General items to watch for.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.
	Ventilation	Determine how your classroom ventilated.	n is Ventilation is working properly.	No corrective action recommended at this time.
223	76.4 <i>Temp</i>	74% 330 <i>RH Co2</i>		
	Excess Moisture in Classrooms	Condensate (condensed water on cold surfaces.	r, or "fog")  There were no problems observed at time of assessment.	No corrective action recommended at this time.
	General Classroom Information		Air fresheners found in room.	Remove air fresheners.
	Thermal Comfort	General items to watch for.	Temperature was slightly elevated. Windows were open. Teacher advised to close windows.	Custodial staff to ensure that all windows are securely closed.
	Thermal Comfort	Humidity level.	Humidity slightly elevated. Windows were open. Teacher advised to close windows.	Custodial staff to ensure that all windows are securely closed.
500	71.9 <b>Temp</b>	57% 320  RH Co2		
	Excess Moisture in Classrooms  General Classroom Information	Condensate (condensed water on cold surfaces.	There were no problems observed at time of assessment.  Ceiling tiles missing.	No corrective action recommended at this time.  Replace ceiling tiles.

Category	Detail	Assessment Comments	Recommended Corrective Action	
Thermal Comfort	Humidity level.	The humidity was 57% at the time of assessment. The desired humidity level is below 60%.	No corrective action recommended at this time.	