

managing risk with responsibility

Telephone: 754-321-3200

Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

March 17, 200	Signature on File	For Custodial Supervisor Use Only
TO:	Ms. Donna Patton, Principal Dania Elementary School	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Edward See, Project Manager Risk Management Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 124A	

On February 14, 2008 I conducted an assessment of FISH 124A at **Dania Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joel Herbst, Area Superintendent
Valerie Wanza, Area Director
Jeffrey S. Moquin, Director, Risk Management
Bob Sharps, Project Manager, Facilities and Construction Management
Jamie Daniels, Broward Teachers Union
Roy Jarrett, National Federation of Public and Private Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

Time of Day
Fish Temperature Range Relative Humidity Range CO2 Range #Occupants 124A 74.9 72 - 78 41.1 30% - 60% 1141 Max 700 > Ambient 1 Noticeable Odor Yes Visible water damage / staining? Ceiling Type Drywall/Plaster No No No None Wall Type Drywall/tile No No No None Flooring Tile No No No None Clean Minor Dust / Debris Cleaning Ceiling Yes No No No No HVAC Supply Grills No
124A
Noticeable Odor Yes
Ceiling Type
Wall Type Drywall/tile No No No None Clean Minor Dust / Debris Cleaning Corrective Action Required
Flooring Tile
Clean Minor Dust / Debris Cleaning Corrective Action Required Ceiling Yes No No No So
Ceiling Yes No No No Walls Yes No
Walls Yes No No No Flooring Yes No No No No HVAC Supply Grills No No No Ceiling at Supply Yes No No No No No No Grills
Flooring Yes No No No No HVAC Supply Grills N/A NO NO NO NO NO NO Ceiling at Supply Yes No No No Grills
HVAC Supply Grills N/A HVAC Return Grills Yes No No Ceiling at Supply Yes No No Grills
HVAC Return Grills Yes No No No Ceiling at Supply Yes No No Grills
Ceiling at Supply Yes No No Grills
Grills
Surfaces in Room Yes No No
Observations Findings: Restroom - Minor "burnt" smell in room. Exhaust fan was recently replaced. Roof exhaust was unremarkable FISH 124 was checked and there were no signs of microbial growth or water intrusion and environmental parameters were
acceptable.
Recommendations: Site Based Maintenance: - Wipe down restroom with the proper mix of Wexcide disinfectant solution - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

IAQ Assessment

0101

Evaluation Requested February 13, 2008

Location Number