THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

FACSIMILE: (754) 321-4285

TELEPHONE (754) 321-4200

June 28, 2017	Signature on File	For Custodial Supervisor Use Only
	Dr. Lewis C. Jackson, Principal Dania Elementary	Custodial Issues Addressed
		Custodial Issues Not Addressed
FROM:	Alison Witoshynsky, Project Manager Environmental Health & Safety Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On June 27, 2017, I conducted an assessment at Dania Elementary. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

Shelley Meloni, Director, Pre-Construction cc:

Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division

Greg Neiman, Area Supervisor, Zone I Gerald Devio, Supervisor II Custodial Benjamin Osborne, Supervisor II Custodial Mark Murray, Supervisor II Custodial Sam Bays, Director, Maintenance Operations Kurt Wirz, Area Manager Trades

Broward Teachers Union

Federation of Public Employees

IAQ Assessment

Dania Ele	ementary Evaluation Date	te June 27, 2017	Time of Day 1200		
Outdoor Conditions Temperatu	re 86.4 Relative	Humidity 90.4	Ambient CO2 469		
Fish Temperature Rang 201 71.5 72 - 7		Range CO ² % - 60% 462	<u></u>		
Noticeable Odor Yes	Visible water damage / staining?	Visible microbial growth?	Amount of material affected		
Ceiling 2' X 4' Lay in	Yes	Yes	7 missing CT; 1 stained CT		
Walls Plaster	No	No			
Floor Terrazzo					
Terrazzo	No	No			
Ceiling Clean No	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean		
Walls Clean Yes	Inside of Supply	No	Inside of Return		
Flooring Clean No	Duct Clean	NO	Duct Clean No		
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	No			
Trash Removed Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room		
Signs of Pests Yes	Drain Traps Wet	No			
Room Cluttered No	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners No in Room		
Mechanical Equipment Location FISH 202C Mechanical Room Clean No					
Filters Installed Properly Yes	Filters Clean	No	Inside of HVAC Unit Clean No		
Condensate Pan Clean Yes	Cooling Coil Clean	No			
Fresh Air Intake Location	hru exterior wall	▼	Fresh Air Intake Free of Obstruction Yes		
Pollutant Sources Near Air Intake	0	▼	OI ODSTIUCTION		
Observations					

IAQ PROTOCOL NOT COMPLETED PRIOR TO OUR ARRIVAL

HFSP reports bad odor/mold in space, many leaks were reported and WO called in. Two WO awaiting start date, J814524 for special CT cuts, J813847 for roof leaks. Ceiling tiles that fell from ceiling at roof leak area are still on the ground. 1 stained ceiling tile remains in the location. Other ceiling tiles are partially painted. Exterior doors to former Kitchen area of building open and one door to cafeteria area, likely cause of elevated humidity in space.

Corrective Actions to be Completed by Site Based Staff

• • • • • • • • • • • • • • • • • • • •		
Remove and replace stained or painted ceiling tile		
Thoroughly clean debris on flooring	▼	
Clean cobwebs from elevated corners	▼	
Clean light fixture lenses	▼	
Remove, replace, tape & date A/C Filters	▼	
Clean grills on door blowers	▼	
Remove cardboard boxes from adj. room (F-202)	▼	
Keep doors to exterior/kitchen/storage closed	▼	

Corrective Actions to be Completed by PPO

▼
▼
▼
▼
▼
▼
▼
▼