## THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

FACSIMILE: (754) 321-4285

**TELEPHONE (754) 321-4200** 

October 3, 20	Signature on File	For Custodial Supervisor Use Only
TO:	Marina Rashid, Principal  Driftwood Elementary	Custodial Issues Addressed  Custodial Issues Not Addressed
FROM:	Alison Witoshynsky, Project Manager Environmental Health & Safety Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On September 29, 2017, I conducted an assessment at **Driftwood Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

cc: Sam Bays, Director, Maintenance Operations
Shelley Meloni, Director, Pre-Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Greg Neiman, Area Supervisor, Zone 1
Kurt Wirz, Area Manager Trades
Gerald Devio, Supervisor II Custodial
Benjamin Osborne, Supervisor II Custodial
Mark Murray, Supervisor II Custodial
Broward Teachers Union
Federation of Public Employees

Remove cardboard boxes	▼
Store items in plastic containers with lids	▼
	▼
	▼
	▼
	▼
	▼
	▼

## Corrective Actions to be Completed by PPO

Evaluate and repair HVAC system as needed	lacksquare
Set Temperature to 72 - 78 degrees	▼
	lacksquare
	lacksquare
	lacksquare
	lacksquare
	▼
	▼

## **IAQ Assessment**

Driftwood Eleme	entary Evaluation D	ate September 29, 2017	Time of Day 11:38 AM					
Outdoor Conditions Temperature	92.3 Relativ	ve Humidity 72.0	Ambient CO2 467					
Fish         Temperature         Range           886C         77.7         72 - 78	Relative Humidity 49.2 3	Range <u>CO<sup>2</sup></u> 0% - 60% 1530	Range # Occupar MAX 700 > ~12 Ambient	nts				
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected					
Ceiling 2' X 4' Lay in	Yes	No	3 CT (1 cut)	IJ				
Walls Tack Board	No	No	Panel wet under East A/C	J I				
Floor 12" x 12" Vinyl	No	No						
Ceiling Clean Yes Walls Clean Yes	HVAC Supply Grills Clean Inside of Supply	Yes	HVAC Return Grills Clean  Inside of Return No	<u> </u>				
Room Surfaces Clean Yes Yes	Duct Clean Ceiling at Supply Grills Clean		Duct Clean	_				
Trash Removed Yes  Signs of Pests No  Room Cluttered No	Exhaust Fans Working  Drain Traps Wet  Food if Stored in Room is in Sealed Containers	N/A	Unapproved Chemicals / No Cleaners in Room  Air Fresheners in Room	ΞΙ				
Mechanical Equipment Location Win	dow unit		Mechanical Room Clean N/A					
Filters Installed Properly Yes	Filters Clean	Yes	Inside of HVAC Unit Clean No					
Condensate Pan Clean N/A	Cooling Coil Clean	N/A						
Fresh Air Intake Location  Pollutant Sources Near Air Intake  No	ı exterior wall	▼	Fresh Air Intake Free of Obstruction					
Observations								
Tackboard wall under/around A/C on east wall is wet. Small area of tackboard wall on left corner of A/C is wet.  No exterior damage observed.								
Corrective Actions to be Completed by Site Based Staff  Corrective Actions to be Completed by PPO								
Remove and replace stained c	Remove and replace stained ceiling tile ▼ Evaluate and repair cause of water damaged ▼							
If stains return, contact COMPASS			II material	▼				
Clean ceiling grid in front of		·	e wall material as needed	<b>—</b>				
Open and dust/wipe inside of A	VC unit(s) ▼	Install new ceiling til	le upon repair, cuts needed	<b>▼</b>				