Eagle Point Elementary TfS IAQ Walkthrough 4-17-2008

Temp 71.6 RH 44.5 CO2 588

FISH	Answer	Recommendation
203	Pests observed at the time of assessment.	Physical Plant Operation to initiate work order to
		evaluate pest issue within location and take
		appropriate action.
208	Signs of water intrusion. Stained ceiling tiles in	Physical Plant Operations to evaluate for leaks and
	208B.	repair as appropriate and replace ceiling tiles as
		appropriate.
	Computer hardware in FISH 208B. No A/C return	Physical Plant Operations to evaluate and repair as
	installed.	appropriate.
	Caulking on sink backsplash is damaged or missing.	Physical Plant Operations to evaluate and repair as
		appropriate.
212	Signs of water intrusion. Leak identified.	Physical Plant Operations to evaluate for leaks and
		repair as appropriate.
213	Gaps in doors identified at the time of assessment -	Physical Plant Operations to evaluate and repair as
	weather strip	appropriate.
222	Signs of water intrusion. Water staining on wall near	Physical Plant Operations to evaluate for leaks and
	teacher desk.	repair as appropriate. Repair/replace wall material as
		appropriate.
229	Carpet was stained, torn, rippled or buckled.	Physical Plant Operations to evaluate and
		repair/replace as appropriate.
306	Gaps in doors identified at the time of assessment -	Physical Plant Operations to evaluate and repair as
	weather strip	appropriate.
	Sink backsplash is water damaged.	Physical Plant Operations to evaluate and repair as
		appropriate.
322	Signs of water intrusion. Leak identified.	Physical Plant Operations to evaluate for leaks and
		repair as appropriate.
331	Multiple stained light fixtures.	Physical Plant Operations to evaluate and repair as
		appropriate.
334	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and
		repair as appropriate and replace ceiling tiles as
		appropriate.
856	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and
		repair as appropriate and replace ceiling tiles as
		appropriate.
	Water staining on floor.	Physical Plant Operations to evaluate and repair as
		appropropriate.