

Tools for Schools - Indoor Air Quality

Follow-up Action Plan for Site



Eagle Ridge Elementary

80.6 44% 350

Principal: Ms. Marina Rashid

Walkthrough Date: 5/7/2004

Temp RH Co2
Outside Measurements

Assignment Member: Aston Henry

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
211	2	Site	There were no leaks identified. However, there are two stained ceiling tiles that need to be replaced.	Install new ceiling tiles.
343	2	Site	The room is extremely stuffy. Return air register grill is very small and has heavy dust and debris.	Custodial staff should clean and sanitize the return registers in this classroom.
345	2	Site	The room is extremely stuffy. Return air register grill is very small and has heavy dust and debris.	Custodial staff should clean and sanitize the return registers in this classroom.