

Temp 72 RH 73.8 CO2 470

<b>FISH</b>	<b>Answer</b>	<b>Recommendation</b>
134A	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
158	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
214	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
215	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
228	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
236	Signs of water intrusion. Stained ceiling tiles and light fixtures.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles and light fixtures as appropriate.
857	Carpet was stained torn rippled or buckled.	Physical Plant Operations to evaluate and repair/replace as appropriate.
859	Signs of water intrusion. Stained ceiling tiles in classroom and restroom.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
P-1380C	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
	Pests observed at the time of assessment.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
	Visible rust on A/C supply vents.	Physical Plant Operation to evaluate and repair as appropriate.
P-1381C	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
P-1379C	Gaps in wall identified at the time of assessment - West wall 1 1/2"	Physical Plant Operations to evaluate and repair/replace as appropriate.
	Damaged window sill.	Physical Plant Operations to evaluate and repair/replace as appropriate.
	Damaged ceiling tiles in restroom.	Physical Plant Operations to evaluate and repair/replace as appropriate.

Temp 72 RH 73.8 CO2 470

<b>FISH</b>	<b>Answer</b>	<b>Recommendation</b>
P-1382C	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
	Damaged ceiling tiles in restroom.	Physical Plant Operations to evaluate and repair/replace as appropriate.
P-1383C unoccupied	Environmental parameters were not within acceptable range at the time of assessment..	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate.
P-QP1400C	Pests observed at the time of assessment.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
	A/C Return vent damaged.	Physical Plant Operations to evaluate and repair/replace as appropriate.
	Environmental parameters were not within acceptable range at the time of assessment..	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate.
P-QP1401C	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
	A/C Return vent damaged.	Physical Plant Operations to evaluate and repair/replace as appropriate.
	Environmental parameters were not within acceptable range at the time of assessment. Thermostat broken.	Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate.