## THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

## **TELEPHONE (754) 321-4200**

## FACSIMILE: (754) 321-4285

March 21, 20	17 Signature on File	For Custodial Supervisor Use Only
TO:	Janice Crosby, Principal Flamingo Elementary	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Alison Witoshynsky, Project Manager Environmental Health & Safety Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On March 20, 2017, I conducted an assessment at **Flamingo Elementary School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

cc: Shelley Meloni, Director, Pre-Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Broward Teachers Union Federation of Public Employees Gerald Devio, Supervisor II Custodial Benjamin Osborne, Supervisor II Custodial Mark Murray, Supervisor II Custodial Sam Bays, Director, Maintenance Operations Kurt Wirz, Area Manager Trades

	IAQ Assess	sment	
Flar	ningo Elementary Evaluation Da	ate March 20, 2017	Time of Day 1246
Outdoor Conditions Te	mperature 78.7 Relativ	ve Humidity 45.4	Ambient CO2 437
FishTemperatureP-518C72.9	······g·	Range       CO <sup>2</sup> 0% - 60%       477	
Noticeable Odor Yes	staining?	Visible microbial growth? No	Amount of material affected 2 Ceiling Panels, 1 cut
Walls Tack Board   Floor 12" x 12" Viny	Yes	No	1 panel under NE A/C
Ceiling Clean Yes Walls Clean Yes	HVAC Supply Grills Clean Inside of Supply	N/a	HVAC Return Grills Clean N/a Inside of Return
Flooring Clean Yes Room Surfaces Yes Clean	Duct Clean Ceiling at Supply Grills Clean	N/A N/a	Duct Clean
Trash RemovedYesSigns of PestsNoRoom ClutteredNo	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers		Unapproved Chemicals / Cleaners in Room Air Fresheners in Room
Mechanical Equipment Location Window/Wall unit Mechanical Room Clean			
Filters Installed Properly Condensate Pan Clean	Yes   Filters Clean     N/A   Cooling Coil Clean	N/A N/A	Inside of HVAC Unit Clean Yes
Fresh Air Intake Location Pollutant Sources Near Air Intake	Behind unit/Exterior wall	▼	Fresh Air Intake Free No
Observations			

Odor upon entry was related to tackboard wall material and portable being closed up for multiple months. The A/C at the NE corner remains on during unoccupied period. Portable very clean. 1 Vinyl tile near center of the room cracked, needs to be replaced. Tackboard panel and wood behind baseboard under NE A/C (newer) shows evidence of historical damage assumed from leaks from old A/C (replaced). Water stain on light lens near NE A/C.

Corrective Actions to be Completed by Site Based Staff

▼
▼
▼
▼
▼
▼
▼
▼

## **Corrective Actions to be Completed by PPO**

Remove and replace stained ceiling tile @ corner		
Evaluate and repair cause of stained ceiling tile	▼	
Install new ceiling tile upon repair, cuts needed	▼	
Remove and replace wall material as needed	▼	
	▼	
	▼	
	▼	
	▼	