

Tools for Schools Phase II - Indoor Air Quality

Follow-up Action Plan for Physical Plant Operations



Flamingo Elementary

67.6 46.7 499

Principal: Ms. Kathleen Morris

Walkthrough Date: 5/9/2005

Temp RH Co2
Outside Measurements

Room	Priority	Responsible	Response	Recommendation
108	2	Physical Plant Operati	Exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
111	2	Physical Plant Operati	Exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
116	2	Physical Plant Operati	Exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as necessary.
116	2	Physical Plant Operati	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
127	1	Physical Plant Operati	No leaks identified. Signs of previous water intrusion as evidenced by staining.	Physical Plant Operations to evaluate and repair as appropriate.
130	1	Physical Plant Operati	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for roof leaks and repair as appropriate.
130	2	Physical Plant Operati	Pests observed at the time of assessment.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
137	2	Physical Plant Operati	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
139	2	Physical Plant Operati	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
141	2	Physical Plant Operati	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
143	2	Physical Plant Operati	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as necessary.
145	2	Physical Plant Operati	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
188	2	Physical Plant Operati	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.