Tools for Schools Phase II - Indoor Air Quality

Follow-up Action Plan for Physical Plant Operations

Fox Trail Elementary 3531 84.3 56.1 448

Walkthrough Date: 5/6/2005 Temp RH Co2
Outside Measurements



Principal: Ms. Linda Chuckman

Room	Priority	Responsible	Response	Recommendation
001	1	Physical Plant Operations	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
001	2	Physical Plant Operations	Odor detected at the time of assessment.	Physical Plant Operations to evaluate cause of odor.
103	2	Physical Plant Operations	Exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
103	2	Physical Plant Operations	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
103D	2	Physical Plant Operations	Exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
103D	2	Physical Plant Operations	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
204	3	Physical Plant Operations	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
209	1	Physical Plant Operations	Signs of water intrusion. Leak identified.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
215	2	Physical Plant Operations	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
216	2	Physical Plant Operations	Bathroom exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.
223	1	Physical Plant Operations	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate.

8/22/2005 Fox Trail Elementary Sorted by Room and Priority Page 1 of 1