THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

FACSIMILE: (754) 321-4285

TELEPHONE (754) 321-4200

August 21, 20	Signature on File	For Custodial Supervisor Use Only
TO:	Keith Peters, Principal Gator Run Elementary	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Alison Witoshynsky, Project Manager Environmental Health & Safety Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On August 17, 2017, I conducted an assessment at **Gator Run Elementary School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

cc: Sam Bays, Director, Maintenance Operations
Shelley Meloni, Director, Pre-Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Greg Neiman, Area Supervisor, Zone 1
Kurt Wirz, Area Manager Trades
Gerald Devio, Supervisor II Custodial
Benjamin Osborne, Supervisor II Custodial
Mark Murray, Supervisor II Custodial
Broward Teachers Union
Federation of Public Employees

IAQ Assessment

Gator Run	Elementary Evaluation Dat	e August 17, 2017	Time of Day 9:55 AM			
Outdoor Conditions Tempera	ature 92.0 Relative	Humidity 64.6	Ambient CO2 458			
	<u> </u>	Range <u>CO</u> % - 60% 499				
Noticeable Odor No Ceiling 2' X 4' Lay in Walls Drywall	Visible water damage / staining? Yes No	Visible microbial growth? No No	Amount of material affected 1 CT by projector			
Floor Carpet	No	No				
Ceiling Clean No Walls Clean Yes Flooring Clean Yes	HVAC Supply Grills Clean Inside of Supply Duct Clean	No N/A	HVAC Return Grills Clean Inside of Return Duct Clean Yes			
Room Surfaces No Clean	Ceiling at Supply Grills Clean	N/a				
Trash Removed Yes Signs of Pests No Room Cluttered Yes	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	N/A N/A	Unapproved Chemicals / No Cleaners in Room Air Fresheners in Room			
Mechanical Equipment Location Filters Installed Properly Condensate Pan Clean Yes	_ _	Yes Yes	Mechanical Room Clean Yes Inside of HVAC Unit Clean Yes			
Fresh Air Intake Location Pollutant Sources Near Air Intake	Not readily accessible Not Accessible	▼	Fresh Air Intake Free of Obstruction			
Observations						
Media Center. Carpet cleaning and wall painting was completed over summer. One ceiling tile by the projector is tained. Stuffed animals and beanbag chairs present. Carpet and wall surfaces appeared clean. Light dust layer on						

top of books and book shelves. Heavy dust under Circulation desk, needs regular vacuuming. Dust layer on backside of return grill at back of room. Light dust on portions of supply vents.

Corrective Actions to be Completed by Site Based Staff

Remove and replace stained ceiling tile		
If stains return, contact COMPASS for work order		
Thoroughly dust horizontal surfaces	▼	
Clean Supply Grills with Wexcide	▼	
Clean dust under desk(s)	▼	
Clean ceilings at ceiling tile grid	▼	
Remove stuffed animals from room which	▼	
can be source of dust allergens	▼	

Corrective Actions to be Completed by PPO

Corrective Actions to be Completed by FFO			
Evaluate and repair HVAC system as needed			
Set Temperature to 72 - 78 degrees			
Repair HVAC to Reduce Humidity Levels			
Vacuum & clean HVAC return grills and drops	▼		
Evaluate and repair cause of stained ceiling tile			
	▼		
	▼		
	▼		