

## managing risk with responsibility

Aston A. Hen		Telephone:	754 321-1900
Risk Manager	ment Department	Fax:	754 321-1917
October 15, 20	O14 Signature on File	For Create dial C	un amicon Hac Only
		For Custodiai S	upervisor Use Only
TO:	Delicia Decembert, Principal	Custodial Iss	ues Addressed
	Hollywood Central Elementary School	Custodial Iss	ues Not Addressed
FROM:	Richard Rosa, Project Manager		
	Risk Management Department		
SUBJECT:	Indoor Air Quality (IAQ) Assessment		

On October 8, 2014, I conducted an assessment at **Hollywood Central Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Director, Risk Management
Sonja Coley, Senior Project Manager, Facilities & Construction
Broward Teachers Union
Federation of Public Employees

RR/tc Enc.

Controlled to be completed by the Bacca t	- tuii
Replace stained ceiling tile by supply vent	▼
Clean HVAC supply grills with Wexcide	▼
Vacuum/wipe return grill	▼
Clean dust on horizontal surfaces	▼
Relocate boxes away from HVAC return grill	▼
	▼
	▼
	▼

▼
▼
▼
▼
▼
▼
▼
▼

▼
▼
▼
▼
▼
▼
▼
▼

▼
▼
▼
▼
▼
▼
▼
▼

Clean dust on horizontal surfaces	▼
Clean HVAC supply grills with Wexcide	▼
Clean ceilings around HVAC supply grills	▼
Monitor insects by windows and treat if necessary	▼
	▼
	▼
	▼
	▼

Clean the HVAC coil	▼
Repair HVAC to reduce humidity level	▼
	▼
	▼
	▼
	▼
	▼
	▼

Clean dust on horizontal surfaces	▼
Clean HVAC supply grills with Wexcide	▼
Clean ceilings around HVAC supply grills	▼
Monitor insects by windows and treat if necessary	▼
Vacuum/wipe return grill	▼
	▼
	lacksquare
	▼

▼
▼
▼
▼
▼
▼
▼
▼

Clean dust on horizontal surfaces	•
Clean HVAC supply grills with Wexcide	▼
Clean ceilings around HVAC supply grills	▼
Vacuum/wipe return grill	▼
	▼
	•
	•
	▼

▼
▼
▼
▼
▼
▼
▼
▼

▼ ▼

▼

ırn grill ▼	Vacuum/wipe retu
▼	
▼	
▼	

▼
▼
▼
▼
▼
▼
▼
▼